



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

GF16MYN - BMW 116D ED PLUS **NAMA** 5

VIN:	WBA1V92040V770144		**Engine No:**	37459512	
Transmission:	Manual	**Odometer:**	101769	**Reg Date:**	30/03/2016
Fuel Type:	Diesel	**Engine CC:**	1496	**Colour:**	SILVER
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Air con	


Tyre Tread Depths

OSF	3.0	**OSR**	3.0	**NSF**	3.0	**NSR**	3.0
Spare		**Type**				**Run Flats**	0

Damage Details


1	**Centre Console Front**	Torn Over 10mm	Replace
2	**Wheel nsr**	Scratched Over 50mm	Smart Repair
3	**Wheel osr**	Scratched Over 50mm	Smart Repair
4	**Wing nsf**	Dented Over 30mm	Repair and Refinish
5	**Door nsf**	Dented With Paint Damage	Repair and Refinish
6	**Wheel nsf**	Scratched Over 50mm	Smart Repair
7	**Wheel osf**	Scratched Over 50mm	Smart Repair
8	**Roof**	Dented Over 30mm	Repair and Refinish
9	**Door osf**	Chipped Edge Chip	Smart Repair
10	**Bumper Rear**	Dented With Paint Damage	Repair and Refinish
11	**B Post os**	Dented With Paint Damage	Repair and Refinish
12	**Qtr Panel nsr**	Dented With Paint Damage	Repair and Refinish
13	**B Post ns**	Dented Between 10mm + 30mm	Smart Repair
14	**B Post ns**	Scratched UpTo 25mm Thru Paint	Report Only
15	**Door Pad nsf**	Scuffed UpTo 25mm	Smart Repair
16	**Tailgate Pad**	Scuffed Over 25mm	Smart Repair

Sectional Damage Summary



17	**Fogdriving Lamp osf**	Broken Replace	Replace
18	**Door osr**	Dented Between 10mm + 30mm	Smart Repair
19	**Screen Front**	Chipped Over 10mm	Replace
20	**Door Pad osf**	Scuffed Over 25mm	Smart Repair
21	**Bumper Front**	Scratched Over 100mm Thru Paint	Refinish
22	**Door nsr**	Dented With Paint Damage	Repair and Refinish

Damage Images


1

Centre Console Front

2

Wheel nsr

3

Wheel osr

4

Wing nsf

5

Door nsf

5

Door nsf

6


Wheel nsf

7

Wheel osf

8

Roof





9

Door osf

10


Bumper Rear

10


Bumper Rear

10  Bumper Rear	11  B Post os	12  Qtr Panel nsr	12  Qtr Panel nsr
13  B Post ns	14  B Post ns	15  Door Pad nsf	16  Tailgate Pad
17  Fogdriving Lamp osf	18  Door osr	19  Screen Front	20  Door Pad osf
21  Bumper Front	21  Bumper Front	21  Bumper Front	22  Door nsr

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Additional	 Additional	 Interior
 OSR Interior	 Dashboard	 Boot	

Inspection Notes :			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford

Inspector's Name:	TW	Date:	23/10/2025