



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

KE72HZX - KIA SORENTO 4 HEV AWD **NAMA** 4

VIN:	KNARH81GSP5161810		**Engine No:**	G4FTNH065360	
Transmission:	Automatic	**Odometer:**	40087	**Reg Date:**	24/02/2023
Fuel Type:	Hybrid/Electric	**Engine CC:**	1598	**Colour:**	BLUE
Body:	Estate	**Seats:**	7	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Sunroof	Panoramic roof
Heated seats	Leather or substitute	AUX/USB	Radio/CD
Cruise control	Climate control	Sat nav	


Tyre Tread Depths

OSF	6.0	**OSR**	4.0	**NSF**	5.0	**NSR**	4.0
Spare	3.0	**Type**	Space Saver			**Run Flats**	0

Damage Details

1	**Wheel osr**	Scratched Up To 50mm	Smart Repair
2	**Wing nsf**	Dented Over 30mm	Repair and Refinish
3	**Door Mirror Assy osf**	Scratched (Painted) UpTo 25mm Thru Paint	Smart Repair
4	**Wheel nsf**	Scratched Over 50mm	Smart Repair
5	**Wheel osf**	Scratched Over 50mm	Smart Repair
6	**Bumper Rear**	Scratched Over 100mm Thru Paint	Refinish
7	**Door osf**	Dented 2 Or Less UpTo 10mm	Smart Repair
8	**Tailgate**	Dented Over 30mm	Repair and Refinish
9	**Qtr Panel osr**	Dented With Paint Damage	Repair and Refinish
10	**B Post os**	Scratched UpTo 25mm Thru Paint	Smart Repair
11	**Bumper Front Grill**	Broken Replace	Replace
12	**Bumper Rear Moulding**	Scuffed (Unpainted) Over 100mm	Smart Repair
13	**Fogdriving Lamp nsf**	Broken Replace	Replace
14	**Bumper Front**	Scratched Over 100mm Thru Paint	Refinish
15	**Door nsr**	Dented With Paint Damage	Repair and Refinish

Sectional Damage Summary



Damage Images

1


Wheel osr

2

Wing nsf

2

Wing nsf

3

Door Mirror Assy osf

4

Wheel nsf

5

Wheel osf

6


Bumper Rear

7

Door osf

8


Tailgate

9

Qtr Panel osr

9

Qtr Panel osr

10

B Post os

11

Bumper Front Grill

12

Bumper Rear Moulding

13

Fogdriving Lamp nsf

14

Bumper Front

14

Bumper Front

14

Bumper Front

15

Door nsr

15

Door nsr

Beauty Images


OSF


NSF


OSR



NSR


Dashboard


Additional


Front Interior


Load Area



Rear Interior

Inspection Notes :			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RM	**Date:**	16/10/2025