



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

KJ17DSY - LAND ROVER RANGE **NAMA** 4

VIN:	SALVB2CN8HH250966		**Engine No:**	170502W0315204DT	
Transmission:	Manual	**Odometer:**	88645	**Reg Date:**	21/07/2017
Fuel Type:	Diesel	**Engine CC:**	1999	**Colour:**	GREY
Body:	Estate	**Seats:**	5	**Spare Keys:**	1

Key Specification

Towbar	Alloys	Parking sensors	Heated windscreen
Heated seats	Leather or substitute	AUX/USB	Radio/CD
Cruise control	Climate control	Air con	


Tyre Tread Depths

OSF	3.0	**OSR**	3.0	**NSF**	3.0	**NSR**	3.0
Spare		**Type**	None			**Run Flats**	0

Damage Details


1	**A Post ns**	Scratched Over 25mm Not Thru Paint	Machine Polish
	Door Mirror Assy osf	Scratched (Painted) UpTo 25mm Thru Paint	Smart Repair
2	**In Car Entertainment**	Broken Replace	Replace
3	**Door Mirror Assy nsf**	Scratched (Painted) Over 25mm Not Thru Paint	Machine Polish
4	**Seat Back Cover nsf**	Scuffed Over 25mm	Smart Repair
	Wheel osf	Scratched Up To 50mm	Smart Repair
5	**Door Window nsf**	Scratched Over 30mm	Replace
6	**Moulding nsf Wing**	Broken Replace	Replace
7	**Roof**	Dented Between 10mm + 30mm	Smart Repair
8	**C Post os**	Scratched UpTo 25mm Thru Paint	Smart Repair
	Bonnet	Scratched Over 25mm Not Thru Paint	Machine Polish
9	**Door osf**	Dented Over 30mm	Repair and Refinish
	Qtr Panel osr	Scratched UpTo 25mm Thru Paint	Smart Repair
	Screen Front	Chipped UpTo 10mm	Smart Repair
10	**Fogdriving Lamp nsf**	Broken Replace	Replace
11	**Bumper Front**	Scratched 25 to 100mm Thru Paint	Smart Repair

Sectional Damage Summary




	Bumper Front	Previous Repair	Report Only
12	**Door nsr**	Dented Over 30mm	Repair and Refinish

Damage Images

1  A Post ns	2  In Car Entertainment	3  Door Mirror Assy nsf	4  Seat Back Cover nsf
5  Door Window nsf	6  Moulding nsf Wing	7  Roof	8  C Post os
9  Door osf	10  Fogdriving Lamp nsf	11  Bumper Front	12  Door nsr

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Additional	 Interior	 Load Area
 OSR Interior	 Dashboard		

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	21/10/2025