



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

KM21XNN - CITROEN C4 SENSE +

NAMA 4

VIN:	VR7BAHNSAME011336		**Engine No:**	TMA60084010	
Transmission:	Manual	**Odometer:**	44818	**Reg Date:**	31/03/2021
Fuel Type:	Petrol	**Engine CC:**	1200	**Colour:**	GREY
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	Leather or substitute	AUX/USB
Radio/CD	Cruise control	Climate control	Air con
Sat nav			


Tyre Tread Depths

OSF	6.0	**OSR**	5.0	**NSF**	6.0	**NSR**	5.0
Spare		**Type**	None			**Run Flats**	0

Damage Details


1	**General Interior**	Soiled Light	Clean
2	**Carpets Front**	Soiled Heavy	Replace
3	**Carpets Front**	Holed Over 3mm	Report Only
4	**Wheel nsr**	Scratched Over 50mm	Smart Repair
5	**Door nsf**	Poor Previous Repair Poor Paint	Refinish
6	**Wheel nsf**	Scratched Over 50mm	Smart Repair
	Moulding nsf Wing	Scuffed (Unpainted) UpTo 100mm	Smart Repair
7	**Wheel osf**	Scratched Over 50mm	Smart Repair
8	**Roof**	Scratched Over 25mm Thru Paint	Refinish
	Bonnet	Chipped 1 To 5	Smart Repair
	Bonnet	Scratched Over 25mm Not Thru Paint	Report Only
9	**Door osf**	Poor Previous Repair Poor Paint	Refinish
10	**Bumper Rear**	Dented With Paint Damage	Repair and Refinish
11	**Qtr Panel Moulding os**	Scuffed (Unpainted) Over 100mm	Smart Repair
12	**Tailgate**	Scratched UpTo 25mm Thru Paint	Smart Repair
13	**Tailgate**	Scratched Over 25mm Not Thru Paint	Report Only

Sectional Damage Summary



14	**Qtr Panel osr**	Scratched Over 25mm Not Thru Paint	Machine Polish
	Qtr Panel nsr	Previous Repair	Report Only
15	**Door osr**	Scratched Over 25mm Thru Paint	Refinish
16	**Bumper Rear Moulding**	Scuffed (Unpainted) Over 100mm	Smart Repair
17	**Bumper Rear Moulding**	Scratched (Painted) Over 25mm Thru Paint	Report Only
18	**Bumper Front**	Scratched Over 100mm Thru Paint	Refinish
19	**Door nsr**	Poor Previous Repair Poor Paint	Refinish

Damage Images

1

General Interior

2

Carpets Front

3


Carpets Front


4

Wheel nsr

5




Door nsf

6

Wheel nsf




7

Wheel osf

8

Roof

9  Door osf	10  Bumper Rear	10  Bumper Rear	11  Qtr Panel Moulding os
12  Tailgate	13  Tailgate	14  Qtr Panel osr	15  Door osr
16  Bumper Rear Moulding	17  Bumper Rear Moulding	18  Bumper Front	19  Door nsr

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Additional	 Interior	 Load Area
 OSR Interior	 Dashboard		

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	22/10/2025