



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

KN16OHW - HONDA HR-V EX I-DTEC **NAMA** 2

VIN:	3HGRU8790GM304480		**Engine No:**	N16A31114842	
Transmission:	Manual	**Odometer:**	116099	**Reg Date:**	15/06/2016
Fuel Type:	Diesel	**Engine CC:**	1597	**Colour:**	BLACK
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Sunroof	Heated seats
Leather or substitute	Radio/CD	Cruise control	Climate control
Air con	Sat nav		


Tyre Tread Depths

OSF	5.0	**OSR**	6.0	**NSF**	5.0	**NSR**	6.0
Spare		**Type**	Inflation Kit			**Run Flats**	0


Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Wheel osf**	Scratched Over 50mm	Smart Repair
	General Interior	Soiled Light	Clean
3	**C Post os**	Dented 2 Or Less UpTo 10mm	Smart Repair
4	**Door osf**	Dented Over 2 UpTo 10mm	Smart Repair
5	**Wheel nsr**	Scratched Over 50mm	Smart Repair
6	**Wheel osr**	Scratched Over 50mm	Smart Repair
7	**B Post os**	Dented Over 2 UpTo 10mm	Smart Repair
8	**B Post ns**	Dented Over 2 UpTo 10mm	Smart Repair
9	**Door osr**	Scratched Over 25mm Not Thru Paint	Machine Polish
10	**Door nsf**	Scratched Over 25mm Not Thru Paint	Machine Polish
11	**C Post ns**	Scratched UpTo 25mm Thru Paint	Smart Repair
12	**Door nsr**	Dented Over 30mm	Repair and Refinish

Sectional Damage Summary



Damage Images

1  Wheel nsf	2  Wheel osf	3  C Post os	4  Door osf
5  Wheel nsr	6  Wheel osr	7  B Post os	8  B Post ns
9  Door osr	10  Door nsf	11  C Post ns	12  Door nsr

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Front Interior	 Rear Interior
 Load Area			

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	TW	**Date:**	23/10/2025