



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

KO66DZZ - PEUGEOT 3008 GT LINE S/S **NAMA** 2

VIN:	VF3MRHNYHGS317997		**Engine No:**	XTA10526038	
Transmission:	Manual	**Odometer:**	70340	**Reg Date:**	12/01/2017
Fuel Type:	Petrol	**Engine CC:**	1200	**Colour:**	WHITE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Heated seats	Leather or substitute
AUX/USB	Radio/CD	Cruise control	Climate control
Sat nav			


Tyre Tread Depths

OSF	4.0	**OSR**	5.0	**NSF**	4.0	**NSR**	5.0
Spare	3.0	**Type**	Space Saver			**Run Flats**	0

Damage Details


1	**Qtr Panel osr**	Dented Over 30mm	Repair and Refinish
2	**Screen Front**	Chipped UpTo 10mm	Smart Repair
3	**Door nsf**	Dented Between 10mm + 30mm	Smart Repair
4	**Bumper Front**	Chipped 1 To 5	Smart Repair

Sectional Damage Summary



Damage Images

1



Qtr Panel osr

2




Screen Front

3



Door nsf

4



Bumper Front

Beauty Images



OSF



NSF




OSR



NSR



Dashboard




Additional



Front Interior



Load Area



Rear Interior

Inspection Notes :			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	MM	**Date:**	16/10/2025