



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

KP68VCE - MERCEDES-BENZ C 300 **NAMA** 2

VIN:	WDD2053832F786733		**Engine No:**	26492030026628	
Transmission:	Automatic	**Odometer:**	52042	**Reg Date:**	28/09/2018
Fuel Type:	Petrol	**Engine CC:**	1991	**Colour:**	WHITE
Body:	Coupe	**Seats:**	4	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	Heated seats	Leather or substitute
AUX/USB	Radio/CD	Cruise control	Climate control
Air con			


Tyre Tread Depths

OSF	2.0	**OSR**	3.0	**NSF**	4.0	**NSR**	2.0
Spare		**Type**	None			**Run Flats**	0


Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
	Roof	Dented Between 10mm + 30mm	Smart Repair
2	**Roof**	Scratched Over 25mm Not Thru Paint	Report Only
	Door osf	Previous Repair	Report Only
	Bumper Rear	Scratched Up To 25mm Thru Paint	Smart Repair
	Wheel osr	Scratched Up To 50mm	Smart Repair
	Qtr Panel osr	Dented Between 10mm + 30mm	Smart Repair
	Qtr Panel osr	Previous Repair	Report Only
3	**Tyre osf**	Less Than 1.6mm Illegal	Replace
	Screen Front	Chipped UpTo 10mm	Smart Repair
4	**Bumper Front**	Scratched Over 100mm Thru Paint	Refinish

Sectional Damage Summary



Damage Images

1 
Wheel nsf

2 
Roof

3 
Tyre osf

4 
Bumper Front

4 
Bumper Front

Beauty Images



OSF



NSF


OSR



NSR


Dashboard


Additional


Interior


Load Area


OSR Interior

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	14/10/2025