



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

TW15TEA - MERCEDES-BENZ C 220 **NAMA** 2

VIN:	W1K2054142F994395		**Engine No:**	65492080731820	
Transmission:	Automatic	**Odometer:**	27012	**Reg Date:**	24/06/2020
Fuel Type:	Diesel	**Engine CC:**	1950	**Colour:**	BLUE
Body:	Convertible	**Seats:**	4	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Heated seats	Leather or substitute
AUX/USB	Radio/CD	Cruise control	Climate control
Air con	Sat nav		


Tyre Tread Depths

OSF	6.0	**OSR**	5.0	**NSF**	5.0	**NSR**	5.0
Spare		**Type**	Inflation Kit			**Run Flats**	0

Damage Details

1	**Bonnet**	Poor Previous Repair Poor Paint	Refinish
2	**Wheel nsr**	Corroded Light	Smart Repair
	Wheel osr	Scratched Up To 50mm	Smart Repair
3	**Door nsf**	Scratched UpTo 25mm Thru Paint	Smart Repair



Sectional Damage Summary



Damage Images

1  Bonnet	2  Wheel nsr	3  Door nsf

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Front Interior	 Rear Interior
 Load Area			

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RM	**Date:**	21/10/2025