



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

LA19WUX - CITROEN C3 FLAIR **NAMA** 3

VIN:	VF7SXHMRVKT599183		**Engine No:**	XVA70313590	
Transmission:	Manual	**Odometer:**	64723	**Reg Date:**	31/05/2019
Fuel Type:	Petrol	**Engine CC:**	1199	**Colour:**	GREY
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Air con	


Tyre Tread Depths

OSF	6.0	**OSR**	5.0	**NSF**	5.0	**NSR**	3.0
Spare	7.0	**Type**	Steel			**Run Flats**	0

Damage Details


1	**Seat Base Cover osr**	Soiled Light	Clean
2	**Seat Base Cover nsr**	Scuffed UpTo 25mm	Smart Repair
3	**Wheel nsr**	Scratched Over 50mm	Smart Repair
4	**Wing osf**	Dented Over 30mm	Repair and Refinish
5	**Door nsf**	Scratched Over 25mm Not Thru Paint	Machine Polish
6	**Wheel nsf**	Corroded Light	Smart Repair
7	**Wheel osf**	Scratched Over 50mm	Smart Repair
8	**Roof**	Dented Between 10mm + 30mm	Smart Repair
9	**Roof**	Scratched Over 25mm Not Thru Paint	Report Only
10	**Door osf**	Chipped Edge Chip	Smart Repair
11	**Bumper Rear**	Scratched Over 25mm Not Thru Paint	Machine Polish
12	**Qtr Panel Moulding ns**	Scuffed (Unpainted) Over 100mm	Smart Repair
13	**Door Pad osr**	Scuffed Over 25mm	Smart Repair
14	**Tailgate**	Scratched Over 25mm Not Thru Paint	Machine Polish
15	**Qtr Panel nsr**	Scratched Over 25mm Not Thru Paint	Machine Polish
16	**Seat Base Cover nsf**	Soiled Light	Clean

Sectional Damage Summary



17	**Door osr**	Scratched Over 25mm Not Thru Paint	Machine Polish
18	**Tailgate Pad**	Scuffed UpTo 25mm	Smart Repair
19	**Bumper Front**	Scratched 25 to 100mm Thru Paint	Smart Repair
20	**Rear Panel Trim Int**	Scuffed Over 25mm	Smart Repair
21	**Door nsr**	Dented With Paint Damage	Repair and Refinish

Damage Images

1

Seat Base Cover osr

2

Seat Base Cover nsr

3

Wheel nsr

4

Wing osf

5

Door nsf

6

Wheel nsf

7

Wheel osf

8

Roof

9

Roof

10

Door osf

11

Bumper Rear


12

Qtr Panel Moulding ns

13 
Door Pad osr

14 
Tailgate

15 
Qtr Panel nsr

16 
Seat Base Cover nsf

17 
Door osr

18 
Tailgate Pad

19 
Bumper Front

20 
Rear Panel Trim Int

21 
Door nsr

Beauty Images


OSF



NSF


OSR


NSR


Dashboard


Additional


Front Interior


Rear Interior


Load Area

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	08/10/2025