



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

LA19XFN - CITROEN C3 FLAIR **NAMA** 2

VIN:	VF7SXHMRVKT596478		**Engine No:**	XVA70311768	
Transmission:	Manual	**Odometer:**	64932	**Reg Date:**	31/05/2019
Fuel Type:	Petrol	**Engine CC:**	1199	**Colour:**	BLUE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Air con	


Tyre Tread Depths

OSF	5.0	**OSR**	3.0	**NSF**	5.0	**NSR**	6.0
Spare	7.0	**Type**	Steel			**Run Flats**	0

Damage Details


1	**Seat Base Cover nsr**	Soiled Light	Clean
2	**Shelfload Cover Rear**	Missing Replace	Replace
3	**Wheel nsr**	Scratched Over 50mm	Smart Repair
4	**Wing osf**	Dented Between 10mm + 30mm	Smart Repair
5	**Door nsf**	Dented Between 10mm + 30mm	Smart Repair
6	**Door nsf**	Chipped Edge Chip	Report Only
7	**Door nsf**	Scratched Over 25mm Not Thru Paint	Report Only
8	**Door Mirror Assy nsf**	Scratched (Painted) UpTo 25mm Thru Paint	Smart Repair
9	**Wheel nsf**	Scratched Over 50mm	Smart Repair
10	**Wheel osf**	Scratched Over 50mm	Smart Repair
11	**Roof**	Scratched Over 25mm Thru Paint	Refinish
12	**Bonnet**	Scratched Over 25mm Not Thru Paint	Machine Polish
13	**Door osf**	Chipped Edge Chip	Smart Repair
14	**Door osf**	Scratched Over 25mm Not Thru Paint	Report Only
15	**BOOT Aperture Seal**	Broken	Unknown
16	**Bumper Rear**	Scratched Up To 25mm Thru Paint	Smart Repair

Sectional Damage Summary



17	**Tailgate**	Scratched Over 25mm Not Thru Paint	Machine Polish
18	**Seat Base Cover osf**	Soiled Light	Clean
19	**Qtr Panel osr**	Scratched Over 25mm Not Thru Paint	Machine Polish
20	**Seat Base Cover nsf**	Soiled Light	Clean
21	**Door osr**	Scratched Over 25mm Not Thru Paint	Machine Polish
22	**Tailgate Pad**	Scuffed Over 25mm	Smart Repair
23	**Flasher Side Repeater os**	Broken Replace	Replace
24	**Door nsr**	Chipped Edge Chip	Smart Repair
25	**Door nsr**	Scratched Over 25mm Not Thru Paint	Report Only

Damage Images

1

Seat Base Cover nsr

2

Shelfload Cover Rear

3

Wheel nsr

4


Wing osf

5

Door nsf

6

Door nsf

7




Door nsf

8

Door Mirror Assy nsf

9  Wheel nsf	10  Wheel osf	11  Roof	11  Roof
12  Bonnet	13  Door osf	14  Door osf	15  BOOT Aperture Seal
16  Bumper Rear	17  Tailgate	17  Tailgate	18  Seat Base Cover osf
19  Qtr Panel osr	20  Seat Base Cover nsf	21  Door osr	22  Tailgate Pad
23  Flasher Side Repeater os	24  Door nsr	25  Door nsr	

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Front Interior	 Rear Interior



Load Area

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	09/10/2025