



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

LA19XHZ - CITROEN C3 FLAIR **NAMA** 4

VIN:	VF7SXHMRVKT598128		**Engine No:**	XVA70315564	
Transmission:	Manual	**Odometer:**	59387	**Reg Date:**	31/05/2019
Fuel Type:	Petrol	**Engine CC:**	1199	**Colour:**	BLUE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Air con	


Tyre Tread Depths

OSF	4.0	**OSR**	3.0	**NSF**	4.0	**NSR**	3.0
Spare		**Type**	Space Saver			**Run Flats**	0

Damage Details


	Shelfload Cover Rear	Missing Replace	Replace
1	**Wheel nsr**	Scratched Over 50mm	Smart Repair
2	**Wheel osr**	Scratched Over 50mm	Smart Repair
3	**Door nsf**	Scratched Over 25mm Not Thru Paint	Machine Polish
4	**Wheel nsf**	Scratched Over 50mm	Smart Repair
5	**Wheel osf**	Scratched Over 50mm	Smart Repair
6	**Roof**	Scratched Over 25mm Thru Paint	Refinish
7	**Bonnet**	Dented Over 30mm	Repair and Refinish
8	**Door osf**	Chipped Edge Chip	Smart Repair
9	**Door osf**	Scratched Over 25mm Not Thru Paint	Report Only
10	**Bumper Rear**	Scratched 25 to 100mm Thru Paint	Smart Repair
11	**Qtr Panel Moulding os**	Scuffed (Unpainted) UpTo 100mm	Smart Repair
12	**Tailgate**	Scratched Over 25mm Not Thru Paint	Machine Polish
13	**Qtr Panel nsr**	Dented Between 10mm + 30mm	Smart Repair
14	**Front TowEye Cvr**	Missing Replace	Replace
15	**Door osr**	Scratched Over 25mm Not Thru Paint	Machine Polish

Sectional Damage Summary



16	**Bumper Rear Moulding**	Scuffed (Unpainted) Over 100mm	Smart Repair
17	**Load Area Carpet**	Broken Replace	Replace
18	**Sill ns**	Dented Over 30mm	Repair and Refinish
19	**Bumper Front**	Insecure Action Required	Smart Repair
	Bumper Front	Chipped Multiple Chips	Report Only
	Bumper Front	Previous Repair	Report Only
20	**Door nsr**	Scratched Over 25mm Not Thru Paint	Machine Polish

Damage Images

1

Wheel nsr

2

Wheel osr

3

Door nsf

4

Wheel nsf

5


Wheel osf

6

Roof

7

Bonnet

8

Door osf

9


Door osf

10

Bumper Rear

10

Bumper Rear

11

Qtr Panel Moulding os

12


Tailgate

13

Qtr Panel nsr

14

Front TowEye Cvr

15

Door osr

16

Bumper Rear Moulding

17


Load Area Carpet

18

Sill ns

19


Bumper Front

20

Door nsr


Beauty Images


OSF



NSF


OSR


NSR


Interior


Load Area


OSR Interior

Inspection Notes : D			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RM	**Date:**	09/10/2025