



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

LA19XPD - CITROEN C3 FLAIR **NAMA** 3

VIN:	VF7SXHMRVKT596503		**Engine No:**	XVA70313142	
Transmission:	Manual	**Odometer:**	71938	**Reg Date:**	31/05/2019
Fuel Type:	Petrol	**Engine CC:**	1199	**Colour:**	GREY
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Air con	


Tyre Tread Depths

OSF	5.0	**OSR**	6.0	**NSF**	4.0	**NSR**	5.0
Spare	7.0	**Type**	Steel			**Run Flats**	0

Damage Details


1	**Seat Base Cover osr**	Soiled Light	Clean
2	**Carpets Front**	Soiled Light	Clean
3	**Seat Base Cover nsr**	Soiled Light	Clean
4	**Shelfload Cover Rear**	Damaged Replace	Replace
5	**Wheel nsr**	Scratched Over 50mm	Smart Repair
6	**Door nsf**	Dented Between 10mm + 30mm	Smart Repair
7	**Door nsf**	Chipped Edge Chip	Report Only
8	**Door nsf**	Scratched Over 25mm Not Thru Paint	Report Only
9	**Wheel nsf**	Scratched Over 50mm	Smart Repair
10	**Wheel osf**	Scratched Over 50mm	Smart Repair
11	**Roof**	Scratched Over 25mm Not Thru Paint	Machine Polish
12	**Bonnet**	Scratched Over 25mm Not Thru Paint	Machine Polish
13	**Door osf**	Chipped Edge Chip	Smart Repair
14	**Bumper Rear**	Scratched 25 to 100mm Thru Paint	Smart Repair
15	**Tailgate**	Scratched Over 25mm Not Thru Paint	Machine Polish
16	**Seat Base Cover osf**	Soiled Light	Clean

Sectional Damage Summary



17	**Qtr Panel nsr**	Dented Over 30mm	Repair and Refinish
18	**Door osr**	Scratched Over 25mm Thru Paint	Refinish
19	**Tailgate Pad**	Scuffed Over 25mm	Smart Repair
20	**Bumper Rear Moulding**	Scuffed (Unpainted) Over 100mm	Smart Repair
21	**Flasher Side Repeater ns**	Broken Replace	Replace
22	**Rear Panel Trim Int**	Scuffed Over 25mm	Smart Repair
23	**Door nsr**	Dented 2 Or Less UpTo 10mm	Smart Repair
24	**Door nsr**	Scratched Over 25mm Not Thru Paint	Report Only

Damage Images

1

Seat Base Cover osr

2

Carpets Front

3

Seat Base Cover nsr

4

Shelfload Cover Rear

5

Wheel nsr

6


Door nsf

7

Door nsf

8

Door nsf

9

Wheel nsf

10

Wheel osf

11

Roof

12

Bonnet

13

Door osf

14


Bumper Rear

14

Bumper Rear

15

Tailgate

16

Seat Base Cover osf

17

Qtr Panel nsr

18

Door osr

19

Tailgate Pad

20

Bumper Rear Moulding

21

Flasher Side Repeater ns

22

Rear Panel Trim Int

23

Door nsr

24

Door nsr

Beauty Images


OSF


NSF


OSR


NSR


Dashboard


Additional


Front Interior


Rear Interior



Load Area

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	09/10/2025