



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

LCV

LM71AOJ - MAXUS E DELIVER 3

NAMA 4

VIN:	LSH14C4C2MA050428		**Engine No:**	44LB076056	
Transmission:	Automatic	**Odometer:**	38175	**Reg Date:**	12/10/2021
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	WHITE
Body:	LCV	**Seats:**	2	**Spare Keys:**	1

Key Specification

Parking sensors	AUX/USB	Radio/CD	Cruise control
Air con			


Tyre Tread Depths

OSF	5.0	**OSR**	8.0	**NSF**	5.0	**NSR**	8.0
Spare		**Type**	Inflation Kit			**Run Flats**	0

Damage Details


1	**Wing Front Arch Extension ns**	Broken Replace	Replace
2	**Wheel nsr**	Corroded Light	Smart Repair
3	**Wheel osr**	Corroded Light	Smart Repair
4	**Wing nsf**	Dented Over 30% Of Panel	Replace
5	**Wheel nsf**	Corroded Light	Smart Repair
6	**Wheel osf**	Corroded Light	Smart Repair
7	**D Post os**	Scratched UpTo 25mm Thru Paint	Smart Repair
8	**Bonnet**	Scratched UpTo 25mm Thru Paint	Smart Repair
9	**Bumper Rear**	Hole Over 25mm	Replace
10	**Seat Base Cover osf**	Soiled Light	Clean
11	**Qtr Panel osr**	Dented Between 10mm + 30mm	Smart Repair
12	**Seat Base Cover nsf**	Soiled Light	Clean
13	**B Post ns**	Scratched UpTo 25mm Thru Paint	Smart Repair
14	**Front TowEye Cvr**	Missing Replace	Replace
15	**Screen Front**	Chipped UpTo 10mm	Smart Repair
16	**Bumper Front**	Hole Over 25mm	Replace

Sectional Damage Summary



17	**Door nsr**	Dented Between 10mm + 30mm	Smart Repair
18	**Door nsr**	Dented Between 10mm + 30mm	Report Only

Damage Images

1

Wing Front Arch Extension ns

2

Wheel nsr

3

Wheel osr

4

Wing nsf

5

Wheel nsf

6

Wheel osf

7

D Post os

8

Bonnet

9

Bumper Rear

10

Seat Base Cover osf

11

Qtr Panel osr

12

Seat Base Cover nsf

13

B Post ns

14

Front TowEye Cvr

15


Screen Front

16


Bumper Front

17  Door nsr	18  Door nsr

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Front Interior	 Load Area	 Additional

Inspection Notes :			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	MM	**Date:**	02/10/2025