



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

LCV

LO69ONZ - FORD RANGER WILDTRAK

NAMA 3

VIN:	6FPPXXMJ2PKY18643		**Engine No:**	KY18643	
Transmission:	Automatic	**Odometer:**	57079	**Reg Date:**	29/11/2019
Fuel Type:	Diesel	**Engine CC:**	3198	**Colour:**	SILVER
Body:	Other	**Seats:**	5	**Spare Keys:**	0

Key Specification

Towbar	Alloys	Parking sensors	Heated windscreen
Leather or substitute	AUX/USB	Radio/CD	Cruise control
Climate control	Air con	Sat nav	


Tyre Tread Depths

OSF	4.0	**OSR**	4.0	**NSF**	4.0	**NSR**	4.0
Spare		**Type**	Steel			**Run Flats**	0

Damage Details

1	**Wing osf**	Rusted Over 5mm	Refinish
2	**Wing nsf**	Rusted Over 5mm	Refinish
3	**Door nsf**	Dented Between 10mm + 30mm	Smart Repair
4	**Bumper Front Moulding**	Scratched (Painted) Over 25mm Thru Paint	Smart Repair
5	**Wheel nsf**	Scratched Over 50mm	Smart Repair
6	**Fascia Trim**	Damaged Replace	Replace
7	**Wheel osf**	Scratched Over 50mm	Smart Repair
8	**Door osf**	Dented Between 10mm + 30mm	Smart Repair
9	**Bumper Rear**	Scratched 25 to 100mm Thru Paint	Smart Repair
10	**Tailgate**	Poor Previous Repair Rippled UpTo 30%	Repair and Refinish
11	**Seat Base Cover osf**	Holed Over 3mm	Replace
12	**Qtr Panel osr**	Poor Previous Repair Poor Paint	Refinish
13	**Qtr Panel nsr**	Scratched Over 25mm Thru Paint	Refinish
14	**Screen Front**	Cracked Replace	Replace
	Sill ns	Dented Between 10mm + 30mm	Smart Repair
	Bumper Front	Chipped 1 To 5	Smart Repair

Sectional Damage Summary



Damage Images

1

Wing osf

2

Wing nsf

3

Door nsf

4

Bumper Front Moulding

5

Wheel nsf

6

Fascia Trim

7

Wheel osf

8

Door osf

9

Bumper Rear

10


Tailgate

11

Seat Base Cover osf

12

Qtr Panel osr

13

Qtr Panel nsr

14

Screen Front

Beauty Images


OSF


NSF


OSR


NSR



Speedometer


Additional


Additional


Interior


Load Area


OSR Interior


Dashboard

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	21/10/2025