



# Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

**LT19FPV** - FORD FOCUS TITANIUM **NAMA** 4

| | | | | | |
|---|---|---|---|---|---|
| **VIN:** | WF0NXXGCHNKY61642 | | **Engine No:** | KY61642 | |
| **Transmission:** | Manual | **Odometer:** | 60178 | **Reg Date:** | 26/06/2019 |
| **Fuel Type:** | Petrol | **Engine CC:** | 999 | **Colour:** | BLACK |
| **Body:** | Hatchback | **Seats:** | 5 | **Spare Keys:** | 1 |

## Key Specification

| | | | |
|---|---|---|---|
| Alloys | Parking sensors | Heated windscreen | Heated seats |
| AUX/USB | Radio/CD | Cruise control | Climate control |
| Air con | Sat nav | | |


## Tyre Tread Depths

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **OSF** | 4.0 | **OSR** | 5.0 | **NSF** | 4.0 | **NSR** | 5.0 |
| **Spare** | 4.0 | **Type** | Space Saver | | | **Run Flats** | 0 |

## Damage Details









| | | | |
|---|---|---|---|
| 1 | **Wheel nsr** | Scratched Up To 50mm | Smart Repair |
| 2 | **Boot Lid** | Scratched Over 25mm Not Thru Paint | Machine Polish |
| 3 | **Wing osf** | Poor Previous Repair Poor Paint | Refinish |
| 4 | **A Post ns** | Dented Between 10mm + 30mm | Smart Repair |
| 5 | **Door nsf** | Scratched Over 25mm Thru Paint | Refinish |
| 6 | **Wheel nsf** | Scratched Over 50mm | Smart Repair |
| 7 | **Roof** | Scratched UpTo 25mm Thru Paint | Smart Repair |
| 8 | **Bonnet** | Scratched Over 25mm Thru Paint | Refinish |
| 9 | **Door osf** | Poor Previous Repair Poor Paint | Refinish |
| 10 | **Bumper Rear** | Poor Previous Repair Poor Paint | Refinish |
| 11 | **Qtr Panel osr** | Scratched Over 25mm Not Thru Paint | Machine Polish |
| 12 | **Qtr Panel nsr** | Scratched UpTo 25mm Thru Paint | Smart Repair |
| 13 | **Door osr** | Scratched UpTo 25mm Thru Paint | Smart Repair |
| 14 | **C Post ns** | Scratched Over 25mm Thru Paint | Refinish |
| 15 | **C Post ns** | Dented Between 10mm + 30mm | Report Only |
| 16 | **Bumper Front** | Poor Previous Repair Poor Paint | Refinish |

## Sectional Damage Summary



| | | | |
|---|---|---|---|
| 17 | Door nsr | Scratched UpTo 25mm Thru Paint | Smart Repair |

## Damage Images



| | | | |
|---|---|---|---|
| 1  Wheel nsr | 2  Boot Lid | 3  Wing osf | 4  A Post ns |
| 5  Door nsf | 6  Wheel nsf | 7  Roof | 8  Bonnet |
| 9  Door osf | 10  Bumper Rear | 11  Qtr Panel osr | 12  Qtr Panel nsr |
| 13  Door osr | 14  C Post ns | 15  C Post ns | 16  Bumper Front |

17



Door nsr

## Beauty Images

| | | | |
|---|---|---|---|
|  OSF |  NSF |  OSR |  NSR |
|  Additional |  Interior |  Rear Interior |  Load Area |

| Inspection Notes : | | | |
|---|---|---|---|
| **Conditions:** | Indoor | **Location:** | Aston Barclay Chelmsford |
| **Inspector's Name:** | RM | **Date:** | 16/10/2025 |