



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

LCV

LX22XAD - CITROEN E-BERLINGO 800

NAMA 4

VIN:	VR7EAZKXZNJ562234		**Engine No:**	5TCG0002459	
Transmission:	Automatic	**Odometer:**	13040	**Reg Date:**	22/03/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	WHITE
Body:	LCV	**Seats:**	3	**Spare Keys:**	1

Key Specification

Parking sensors	AUX/USB	Radio/CD	Cruise control
Air con			


Tyre Tread Depths

OSF	3.0	**OSR**	6.0	**NSF**	3.0	**NSR**	5.0
Spare		**Type**	None			**Run Flats**	0


Damage Details

1	**Wheel Trim nsf**	Scratched Up To 50mm	Smart Repair
2	**Bumper Rear**	Cracked Over 25mm	Replace
3	**Door osf**	Dented With Paint Damage	Repair and Refinish
4	**Seat Base Cover osf**	Soiled Light	Clean
5	**Lamp osr**	Broken Replace	Replace
6	**Qtr Panel osr**	Dented Over 30mm	Repair and Refinish
7	**Seat Base Cover nsf**	Soiled Light	Clean
8	**Screen Front**	Cracked Replace	Replace
9	**Door osr**	Dented With Paint Damage	Repair and Refinish
10	**Bumper Front**	Scratched 25 to 100mm Thru Paint	Smart Repair
11	**Wheel Trim nsr**	Scratched Up To 50mm	Smart Repair
12	**Door nsr**	Dented Between 10mm + 30mm	Smart Repair

Sectional Damage Summary



Damage Images

1

Wheel Trim nsf

2

Bumper Rear

3

Door osf

4

Seat Base Cover osf

5

Lamp osr

6

Qtr Panel osr

6

Qtr Panel osr

7

Seat Base Cover nsf

8

Screen Front

9

Door osr

10


Bumper Front

11

Wheel Trim nsr

12

Door nsr

Beauty Images



OSF


NSF


OSR


NSR


Speedometer


Front Interior


Load Area


Dashboard

Inspection Notes : No charging cable			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	MM	**Date:**	20/10/2025