



# Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

**LY23MDU** - FORD PUMA ST-LINE X **NAMA** 3

| | | | | | |
|---|---|---|---|---|---|
| **VIN:** | WF02XXERK2PD03623 | | **Engine No:** | PD03623 | |
| **Transmission:** | Manual | **Odometer:** | 25333 | **Reg Date:** | 31/05/2023 |
| **Fuel Type:** | Petrol | **Engine CC:** | 999 | **Colour:** | GREY |
| **Body:** | Hatchback | **Seats:** | 5 | **Spare Keys:** | 1 |

## Key Specification

| | | | |
|---|---|---|---|
| Alloys | Parking sensors | Heated windscreen | Leather or substitute |
| AUX/USB | Radio/CD | Cruise control | Climate control |
| Air con | Sat nav | | |


## Tyre Tread Depths

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **OSF** | 3.0 | **OSR** | 5.0 | **NSF** | 3.0 | **NSR** | 5.0 |
| **Spare** | | **Type** | Inflation Kit | | | **Run Flats** | 0 |

## Damage Details

| | | | |
|---|---|---|---|
| 1 | **Wheel nsf** | Scratched Over 50mm | Smart Repair |
| 2 | **C Post os** | Dented With Paint Damage | Repair and Refinish |
| 3 | **Bumper Rear** | Poor Previous Repair Poor Paint | Refinish |
| 4 | **Tyre nsf** | Damaged Replace | Replace |
| 5 | **Screen Front** | Chipped Over 10mm | Replace |
| 6 | **Bumper Front** | Scratched Over 25mm Not Thru Paint | Machine Polish |

## Sectional Damage Summary



## Damage Images

1

Wheel nsf

2

C Post os

3


Bumper Rear

4

Tyre nsf

5

Screen Front

6

Bumper Front

## Beauty Images


OSF



NSF


OSR


NSR


Dashboard


Additional


Interior


Load Area


OSR Interior

| Inspection Notes : | | | |
|---|---|---|---|
| **Conditions:** | Indoor | **Location:** | Aston Barclay Chelmsford |
| **Inspector's Name:** | CF | **Date:** | 13/10/2025 |