



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

ME19WCM - PEUGEOT 3008 ALLURE **NAMA** 4

VIN:	VF3MCYHZJKS280795		**Engine No:**	Q3DM0429674	
Transmission:	Manual	**Odometer:**	99740	**Reg Date:**	28/06/2019
Fuel Type:	Diesel	**Engine CC:**	1500	**Colour:**	GREY
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Leather or substitute	AUX/USB
Radio/CD	Cruise control	Climate control	Air con
Sat nav			


Tyre Tread Depths

OSF	5.0	**OSR**	5.0	**NSF**	3.0	**NSR**	5.0
Spare	2.0	**Type**	Space Saver			**Run Flats**	0

Damage Details


1	**Roof**	Dented Over 30mm	Repair and Refinish
2	**Roof**	Dented Over 30mm	Report Only
3	**Bonnet**	Chipped Multiple Chips	Refinish
4	**Door osf**	Chipped Edge Chip	Smart Repair
5	**Door osf**	Dented 2 Or Less UpTo 10mm	Report Only
6	**Qtr Panel osr**	Dented Between 10mm + 30mm	Smart Repair
7	**Qtr Panel nsr**	Poor Previous Repair Poor Paint	Refinish
8	**Seat Base Cover nsf**	Soiled Light	Clean
9	**Door osr**	Chipped Edge Chip	Smart Repair
10	**Door osr**	Dented 2 Or Less UpTo 10mm	Report Only
11	**Tailgate Pad**	Scuffed Over 25mm	Smart Repair
12	**Sill ns**	Dented 2 Or Less UpTo 10mm	Smart Repair
13	**Door nsf**	Dented Between 10mm + 30mm	Smart Repair
14	**Door nsf**	Scratched Over 25mm Not Thru Paint	Report Only
15	**C Post ns**	Dented Over 2 UpTo 10mm	Smart Repair
16	**Seat Back Cover osf**	Torn Over 3mm	Replace

Sectional Damage Summary



17	**Door nsr**	Poor Previous Repair Poor Paint	Refinish

Damage Images

1  Roof	2  Roof	3  Bonnet	4  Door osf
5  Door osf	6  Qtr Panel osr	7  Qtr Panel nsr	8  Seat Base Cover nsf
9  Door osr	10  Door osr	11  Tailgate Pad	12  Sill ns
13  Door nsf	14  Door nsf	15  C Post ns	16  Seat Back Cover osf

17



Door nsr

Beauty Images



OSF



NSF



OSR



NSR



Dashboard



Additional



Front Interior



Rear Interior



Load Area

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	29/09/2025