



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

MF22SFN - MG ZS SE EV

NAMA 5

VIN:	LSJW7409XMZ249563		**Engine No:**	5A10068714	
Transmission:	Automatic	**Odometer:**	13866	**Reg Date:**	31/03/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	SILVER
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Sat nav	


Tyre Tread Depths

OSF	6.0	**OSR**	6.0	**NSF**	5.0	**NSR**	6.0
Spare		**Type**	None			**Run Flats**	0

Damage Details

1	**Shelfload Cover Rear**	Damaged Replace	Replace
2	**Wheel nsr**	Scratched Up To 50mm	Smart Repair
3	**Wheel osr**	Scratched Up To 50mm	Smart Repair
4	**Wing nsf**	Dented Over 30mm	Repair and Refinish
5	**Seat Back Cover nsf**	Holed Over 3mm	Replace
6	**Wheel nsf**	Scratched Over 50mm	Smart Repair
7	**Wheel osf**	Scratched Over 50mm	Smart Repair
8	**General Exterior**	Decals Fitted Body Transfers	Report Only
9	**Bumper Rear**	Cracked Over 25mm	Replace
10	**Tailgate**	Dented Over 30mm	Repair and Refinish
11	**Qtr Panel nsr**	Dented Over 30mm	Repair and Refinish
12	**Aperture Seal nsf**	Broken Replace	Replace
13	**Bumper Front**	Scratched Over 100mm Thru Paint	Refinish
14	**Door nsr**	Dented Over 30mm	Repair and Refinish

Sectional Damage Summary



Damage Images

1 
Shelfload Cover Rear

1 
Shelfload Cover Rear

2 
Wheel nsr

3 
Wheel osr

4 
Wing nsf

5 
Seat Back Cover nsf

6 
Wheel nsf

7 
Wheel osf

8 
General Exterior

8 
General Exterior

8 
General Exterior

8 
General Exterior

8 
General Exterior


8 
General Exterior

8 
General Exterior

9 
Bumper Rear

10 
Tailgate

11 
Qtr Panel nsr

12 
Aperture Seal nsf

13 
Bumper Front

13 
Bumper Front

14 
Door nsr

Beauty Images


OSF


NSF


OSR


NSR

 Dashboard	 Additional	 Front Interior	 Load Area
 Rear Interior	 Additional		

Inspection Notes : Front and rear parking camera's			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	MM	**Date:**	09/10/2025