



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

ND21UUT - VAUXHALL CORSA ELITE **NAMA** 4

VIN:	VXKUPHMHDM4038822		**Engine No:**	10XVAL0121368 O3P	
Transmission:	Manual	**Odometer:**	41522	**Reg Date:**	31/03/2021
Fuel Type:	Petrol	**Engine CC:**	1199	**Colour:**	WHITE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Heated seats	Leather or substitute
AUX/USB	Radio/CD	Cruise control	Air con


Tyre Tread Depths

OSF	4.0	**OSR**	3.0	**NSF**	5.0	**NSR**	6.0
Spare		**Type**	None			**Run Flats**	0

Damage Details


1	**Carpets Front**	Holed Over 3mm	Replace
2	**Seat Base Cover osr**	Soiled Light	Clean
3	**Wheel nsr**	Scratched Over 50mm	Smart Repair
4	**Wheel osr**	Scratched Up To 50mm	Smart Repair
5	**Door Mirror Assy osf**	Broken Replace	Replace
6	**Roof Lining**	Burn UpTo 3mm	Smart Repair
7	**Wheel nsf**	Scratched Over 50mm	Smart Repair
8	**Wheel osf**	Scratched Over 50mm	Smart Repair
9	**Roof**	Dented Over 30mm	Repair and Refinish
10	**Bonnet**	Scratched Over 25mm Not Thru Paint	Machine Polish
11	**Bumper Rear**	Scratched Over 100mm Thru Paint	Refinish
12	**Door osf**	Dented With Paint Damage	Repair and Refinish
13	**Qtr Panel osr**	Dented Between 10mm + 30mm	Smart Repair
	Qtr Panel osr	Previous Repair	Report Only
14	**B Post ns**	Scratched UpTo 25mm Thru Paint	Smart Repair
15	**Tailgate Pad**	Scuffed Over 25mm	Smart Repair

Sectional Damage Summary



16	**Door osr**	Dented Between 10mm + 30mm	Smart Repair
17	**Load Area Carpet**	Soiled Light	Clean
18	**Bumper Front**	Chipped 1 To 5	Smart Repair

Damage Images

1

Carpets Front

2

Seat Base Cover osr

3

Wheel nsr

4

Wheel osr

5

Door Mirror Assy osf

6


Roof Lining


7

Wheel nsf

8

Wheel osf

9

Roof

9

Roof

9

Roof

10

Bonnet

10


Bonnet


11

Bumper Rear

12

Door osf

13

Qtr Panel osr

14

B Post ns

15

Tailgate Pad

16

Door osr

17

Load Area Carpet

18

Bumper Front

18

Bumper Front


Beauty Images



OSF


NSF



OSR


NSR



Service Book


Additional


Dashboard


Front Interior


Load Area


Rear Interior

Inspection Notes :			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RM	**Date:**	15/10/2025