



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

OE22JYO - MG ZS SE EV

NAMA 4

VIN:	LSJW74096NZ168173		**Engine No:**	8A10089171	
Transmission:	Automatic	**Odometer:**	77927	**Reg Date:**	30/06/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	BLUE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Sat nav	


Tyre Tread Depths

OSF	6.0	**OSR**	4.0	**NSF**	6.0	**NSR**	3.0
Spare		**Type**	Inflation Kit			**Run Flats**	0




Damage Details

1	**Shelfload Cover Rear**	Damaged Replace	Replace
2	**Wheel nsr**	Scratched Over 50mm	Smart Repair
3	**Wing osf**	Poor Previous Repair Rippled Over 30%	Repair and Refinish
4	**Wing nsf**	Dented Between 10mm + 30mm	Smart Repair
5	**Door nsf**	Dented Over 30mm	Repair and Refinish
6	**Seat Back Cover osf**	Holed UpTo 3mm	Smart Repair
7	**Wheel nsf**	Scratched Over 50mm	Smart Repair
8	**Wheel osf**	Scratched Over 50mm	Smart Repair
9	**C Post os**	Dented With Paint Damage	Repair and Refinish
10	**Bonnet**	Dented Between 10mm + 30mm	Smart Repair
11	**Door osf**	Poor Previous Repair Rippled UpTo 30%	Repair and Refinish
12	**Seat Base Cover osf**	Scuffed Over 25mm	Smart Repair
13	**Aperture Seal osf**	Broken Replace	Replace
14	**C Post ns**	Dented With Paint Damage	Repair and Refinish
15	**Door nsr**	Dented 2 Or Less UpTo 10mm	Smart Repair


Sectional Damage Summary



Damage Images

1  Shelfload Cover Rear	2  Wheel nsr	3  Wing osf	3  Wing osf
4  Wing nsf	5  Door nsf	6  Seat Back Cover osf	7  Wheel nsf
8  Wheel osf	9  C Post os	10  Bonnet	11  Door osf
12  Seat Base Cover osf	13  Aperture Seal osf	14  C Post ns	15  Door nsr

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Additional	 Front Interior	 Load Area
 Rear Interior	 Dashboard	 Additional	

Inspection Notes : Front and rear parking camera's			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	MM	**Date:**	20/10/2025