



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

OE22NPD - MG ZS SE EV

NAMA 4

VIN:	LSJW74097NZ172202		**Engine No:**	7A10092317	
Transmission:	Automatic	**Odometer:**	99869	**Reg Date:**	30/06/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	RED
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Sat nav	


Tyre Tread Depths

OSF	6.0	**OSR**	5.0	**NSF**	5.0	**NSR**	6.0
Spare		**Type**	None			**Run Flats**	0

Damage Details

1	**Carpets Front**	Scuffed Over 25mm	Smart Repair
2	**Centre Console Front**	Soiled Light	Clean
	Wing Front Arch Extension ns	Scuffed (Unpainted) Over 100mm	Smart Repair
3	**Shelfload Cover Rear**	Missing Replace	Replace
4	**Wing osf**	Dented Between 10mm + 30mm	Smart Repair
5	**Wing nsf**	Dented Between 10mm + 30mm	Smart Repair
6	**Aerial**	Missing Replace	Replace
7	**Door nsf**	Dented With Paint Damage	Repair and Refinish
8	**Bumper Front Moulding**	Scuffed (Unpainted) Over 100mm	Smart Repair
9	**Bumper Front Moulding**	Scratched (Painted) Over 25mm Thru Paint	Report Only
10	**Wheel Trim nsr**	Scratched Over 50mm	Smart Repair
11	**Wheel Trim osr**	Scratched Over 50mm	Smart Repair
12	**Wheel nsf**	Scratched Over 50mm	Smart Repair
13	**Wheel osf**	Scratched Over 50mm	Smart Repair
14	**Wheel Trim osf**	Scratched Up To 50mm	Smart Repair
15	**C Post os**	Dented With Paint Damage	Repair and Refinish

Sectional Damage Summary



16	**Bonnet**	Scratched Over 25mm Thru Paint	Refinish
17	**Bumper Rear**	Chipped 1 To 5	Smart Repair
18	**Door osf**	Dented Between 10mm + 30mm	Smart Repair
19	**Qtr Panel osr**	Dented Between 10mm + 30mm	Smart Repair
20	**Qtr Panel nsr**	Scratched UpTo 25mm Thru Paint	Smart Repair
21	**Door osr**	Dented Over 30mm	Repair and Refinish
22	**Bumper Front**	Scratched Over 100mm Thru Paint	Refinish
23	**Door nsr**	Dented With Paint Damage	Repair and Refinish

Damage Images

1

Carpets Front

2

Centre Console Front

3

Shelfload Cover Rear

4

Wing osf

5

Wing nsf

6


Aerial

7

Door nsf

7

Door nsf

8  Bumper Front Moulding	9  Bumper Front Moulding	10  Wheel Trim nsr	11  Wheel Trim osr
12  Wheel nsf	13  Wheel osf	14  Wheel Trim osf	15  C Post os
16  Bonnet	17  Bumper Rear	18  Door osf	19  Qtr Panel osr
20  Qtr Panel nsr	21  Door osr	22  Bumper Front	23  Door nsr

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Additional	 Front Interior	 Load Area
 Rear Interior	 Dashboard	 Additional	

Inspection Notes : Front and rear cameras			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford

Inspector's Name:	MM	Date:	22/10/2025