



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

OE71NJO - MG 5 EXCITE

NAMA 4

VIN:	LSJE24096MG065694		**Engine No:**	4A10040440	
Transmission:	Automatic	**Odometer:**	81319	**Reg Date:**	26/01/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	RED
Body:	Estate	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Air con	Sat nav	


Tyre Tread Depths

OSF	4.0	**OSR**	6.0	**NSF**	4.0	**NSR**	4.0
Spare		**Type**	None			**Run Flats**	0

Damage Details


1	**Carpets Front**	Holed UpTo 3mm	Smart Repair
2	**Seat Base Cover osr**	Soiled Light	Clean
3	**Seat Base Cover nsr**	Soiled Light	Clean
4	**Wheel nsr**	Scratched Over 50mm	Smart Repair
5	**Wing osf**	Poor Previous Repair Poor Colour	Refinish
6	**Wing nsf**	Poor Previous Repair Poor Paint	Refinish
7	**Door nsf**	Poor Previous Repair Poor Paint	Refinish
8	**Moulding Tailgate**	Broken Replace	Replace
9	**Roof Lining**	Soiled Light	Clean
10	**Aperture Seal nsr**	Broken Replace	Replace
11	**Wheel nsf**	Scratched Over 50mm	Smart Repair
12	**Wheel osf**	Scratched Over 50mm	Smart Repair
13	**Door osf**	Poor Previous Repair Rippled UpTo 30%	Repair and Refinish
14	**Bumper Rear**	Scratched Over 100mm Thru Paint	Refinish
15	**Tailgate**	Dented Over 30mm	Repair and Refinish
16	**Seat Base Cover osf**	Soiled Light	Clean


Sectional Damage Summary




17	**Qtr Panel osr**	Poor Previous Repair Poor Paint	Refinish
18	**Qtr Panel nsr**	Dented Over 2 UpTo 10mm	Smart Repair
19	**Qtr Panel nsr**	Scratched UpTo 25mm Thru Paint	Report Only
20	**Seat Base Cover nsf**	Soiled Light	Clean
21	**Door osr**	Previous Repair	Report Only
22	**Tailgate Pad**	Scuffed UpTo 25mm	Smart Repair
23	**Aperture Seal osf**	Broken Replace	Replace
24	**Sill os**	Scratched UpTo 25mm Thru Paint	Smart Repair
25	**Bumper Front**	Poor Previous Repair Poor Paint	Refinish
26	**Door nsr**	Dented Between 10mm + 30mm	Smart Repair
27	**Door nsr**	Scratched UpTo 25mm Thru Paint	Report Only

Damage Images




1

Carpets Front

2

Seat Base Cover osr


3

Seat Base Cover nsr

4

Wheel nsr

5  Wing osf	6  Wing nsf	7  Door nsf	8  Moulding Tailgate
9  Roof Lining	9  Roof Lining	10  Aperture Seal nsr	11  Wheel nsf
12  Wheel osf	13  Door osf	13  Door osf	14  Bumper Rear
14  Bumper Rear	15  Tailgate	16  Seat Base Cover osf	17  Qtr Panel osr
18  Qtr Panel nsr	19  Qtr Panel nsr	20  Seat Base Cover nsf	21  Door osr
22  Tailgate Pad	23  Aperture Seal osf	24  Sill os	25  Bumper Front
25  Bumper Front	26  Door nsr	27  Door nsr	

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Additional	 Dashboard	 Front Interior
 Rear Interior	 Load Area		

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	20/10/2025