



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

OE71NKJ - MG 5 EXCITE

NAMA 3

VIN:	LSJE24090MG083785		**Engine No:**	8A10049259	
Transmission:	Automatic	**Odometer:**	88233	**Reg Date:**	26/01/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	SILVER
Body:	Estate	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Air con	Sat nav	


Tyre Tread Depths

OSF	3.0	**OSR**	5.0	**NSF**	4.0	**NSR**	5.0
Spare		**Type**	Inflation Kit			**Run Flats**	0


Damage Details

1	**Carpets Front**	Holed Over 3mm	Replace
	Wheel nsr	Scratched Up To 50mm	Smart Repair
2	**Wing nsf**	Dented Between 10mm + 30mm	Smart Repair
3	**Door nsf**	Dented Between 10mm + 30mm	Smart Repair
4	**Wheel nsf**	Scratched Over 50mm	Smart Repair
5	**Wheel osf**	Scratched Over 50mm	Smart Repair
	Bonnet	Previous Repair	Report Only
6	**Qtr Panel osr**	Scratched Over 25mm Not Thru Paint	Machine Polish
7	**Qtr Panel nsr**	Dented Between 10mm + 30mm	Smart Repair
	Door osr	Dented 2 Or Less UpTo 10mm	Smart Repair
	Screen Front	Chipped UpTo 10mm	Smart Repair
8	**Load Area Carpet**	Soiled Light	Clean
9	**Aperture Seal osf**	Broken Replace	Replace
10	**Bumper Front**	Scratched 25 to 100mm Thru Paint	Smart Repair
11	**Door nsr**	Dented Over 30mm	Repair and Refinish

Sectional Damage Summary



Damage Images

1 
Carpets Front

2 
Wing nsf

3 
Door nsf

4 
Wheel nsf

5 
Wheel osf

6 
Qtr Panel osr

7 
Qtr Panel nsr

8 
Load Area Carpet

9 
Aperture Seal osf

10 
Bumper Front

11 
Door nsr

Beauty Images


OSF



NSF


OSR



NSR


Dashboard


Additional


Interior


Load Area


OSR Interior


Additional

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	20/10/2025