



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

OV22KWP - MG 5 EXCITE **NAMA** 4

VIN:	LSJE24095NG024877		**Engine No:**	0A10066964	
Transmission:	Automatic	**Odometer:**	80466	**Reg Date:**	05/05/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	BLUE
Body:	Estate	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Air con	Sat nav	


Tyre Tread Depths

OSF	5.0	**OSR**	5.0	**NSF**	5.0	**NSR**	5.0
Spare		**Type**	Inflation Kit			**Run Flats**	0


Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Roof**	Dented With Paint Damage	Repair and Refinish
3	**Door osf**	Dented With Paint Damage	Repair and Refinish
4	**Seat Base Cover osf**	Holed UpTo 3mm	Smart Repair
	Qtr Panel osr	Dented Between 10mm + 30mm	Smart Repair
	Qtr Panel osr	Previous Repair	Report Only
5	**Qtr Panel nsr**	Dented Over 30mm	Repair and Refinish
	Door osr	Dented Between 10mm + 30mm	Smart Repair
6	**Door osr**	Scratched Over 25mm Not Thru Paint	Report Only
	Door osr	Previous Repair	Report Only
7	**Wing osf**	Poor Previous Repair Rippled UpTo 30%	Repair and Refinish
8	**Bumper Front**	Poor Previous Repair Rippled Over 30%	Repair and Refinish
9	**Bumper Front**	Dented With Paint Damage	Report Only
10	**Door Mirror Assy osf**	Scratched (Painted) Over 25mm Thru Paint	Smart Repair
11	**Door Mirror Assy osf**	Scratched (Painted) Over 25mm Not Thru Paint	Report Only
	Door nsr	Previous Repair	Report Only




Sectional Damage Summary



Damage Images

1  Wheel nsf	2  Roof	3  Door osf	4  Seat Base Cover osf
5  Qtr Panel nsr	6  Door osr	7  Wing osf	8  Bumper Front
9  Bumper Front	10  Door Mirror Assy osf	11  Door Mirror Assy osf	

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Additional	 Additional	 Interior
 Load Area	 OSR Interior	 Dashboard	

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	21/10/2025