



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

OV72FNK - MG ZS SE EV

NAMA 4

VIN:	LSJW74096NZ213791		**Engine No:**	0A10108515	
Transmission:	Automatic	**Odometer:**	56533	**Reg Date:**	23/09/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	RED
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	0

Key Specification

Parking sensors	AUX/USB	Radio/CD	Cruise control
Climate control	Air con	Sat nav	


Tyre Tread Depths

OSF	3.0	**OSR**	4.0	**NSF**	3.0	**NSR**	4.0
Spare		**Type**	None			**Run Flats**	0

Damage Details

1	**Carpets Front**	Holed Over 3mm	Replace
2	**Shelfload Cover Rear**	Damaged Replace	Replace
3	**Wing nsf**	Dented Between 10mm + 30mm	Smart Repair
4	**Door nsf**	Dented Between 10mm + 30mm	Smart Repair
5	**Aperture Seal nsr**	Broken Replace	Replace
6	**Aperture Seal osr**	Broken Replace	Replace
7	**Wheel nsf**	Scratched Over 50mm	Smart Repair
	Roof	Dented Between 10mm + 30mm	Smart Repair
8	**C Post os**	Dented Between 10mm + 30mm	Smart Repair
9	**Bonnet**	Scratched Over 25mm Not Thru Paint	Machine Polish
10	**Door osf**	Dented Between 10mm + 30mm	Smart Repair
11	**Bumper Rear**	Scratched 25 to 100mm Thru Paint	Smart Repair
12	**Tailgate**	Poor Previous Repair Poor Paint	Refinish
13	**Qtr Panel osr**	Poor Previous Repair Poor Paint	Refinish
14	**Qtr Panel nsr**	Dented Over 30mm	Repair and Refinish
15	**C Post ns**	Dented Between 10mm + 30mm	Smart Repair

Sectional Damage Summary



	Bumper Front	Previous Repair	Report Only

Damage Images

1

Carpets Front

2

Shelfload Cover Rear

3

Wing nsf

4

Door nsf

5

Aperture Seal nsr

6

Aperture Seal osr

7

Wheel nsf

8

C Post os

9

Bonnet

10

Door osf

11

Bumper Rear

12

Tailgate

13

Qtr Panel osr

14

Qtr Panel nsr

15

C Post ns

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Interior	 Load Area
 OSR Interior	 Additional		

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	TW	**Date:**	23/10/2025