



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

OV72FOH - MG ZS SE EV

NAMA 3

VIN:	LSJW74092NZ213707		**Engine No:**	0A10108512	
Transmission:	Automatic	**Odometer:**	147498	**Reg Date:**	30/09/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	SILVER
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Parking sensors	AUX/USB	Radio/CD	Cruise control
Climate control	Air con	Sat nav	


Tyre Tread Depths

OSF	3.0	**OSR**	5.0	**NSF**	8.0	**NSR**	7.0
Spare		**Type**	Inflation Kit			**Run Flats**	0

Damage Details

1	**Carpets Front**	Holed Over 3mm	Replace
2	**Rear TowEye Cvr**	Broken Replace	Replace
3	**Door Moulding nsf**	Scuffed (Unpainted) UpTo 100mm	Smart Repair
4	**Door Mirror Assy nsf**	Scratched (Painted) Over 25mm Thru Paint	Smart Repair
5	**Wheel Trim nsr**	Scratched Over 50mm	Smart Repair
6	**Aperture Seal nsr**	Broken Replace	Replace
7	**Wheel Trim osr**	Scratched Over 50mm	Smart Repair
8	**Moulding nsf Wing**	Scuffed (Unpainted) Over 100mm	Smart Repair
9	**Moulding osf Wing**	Broken Replace	Replace
10	**Wheel Trim nsf**	Scratched Over 50mm	Smart Repair
11	**Wheel Trim osf**	Scratched Over 50mm	Smart Repair
12	**Door Pad nsr**	Scuffed Over 25mm	Smart Repair
13	**Bumper Rear**	Dented With Paint Damage	Repair and Refinish
14	**Door osr**	Dented With Paint Damage	Repair and Refinish
15	**Bumper Front**	Scratched 25 to 100mm Thru Paint	Smart Repair

Sectional Damage Summary



Damage Images

1

Carpets Front

2

Rear TowEye Cvr

3

Door Moulding nsf

4

Door Mirror Assy nsf

5

Wheel Trim nsr

6

Aperture Seal nsr

7

Wheel Trim osr

8

Moulding nsf Wing

9

Moulding osf Wing

10

Wheel Trim nsf

11

Wheel Trim osf

12

Door Pad nsr

13

Bumper Rear

14

Door osr

15

Bumper Front


Beauty Images



OSF



NSF



OSR


NSR


Additional


Interior


Rear Interior


Dashboard


Load Area

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	BG	**Date:**	22/10/2025