



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

PF72TUU - VOLKSWAGEN ID3 LIFE **NAMA** 2

VIN:	WVWZZZE1ZPP014332		**Engine No:**	EBJC	
Transmission:	Automatic	**Odometer:**	42126	**Reg Date:**	30/12/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	TURQUOISE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Parking sensors	Heated seats	Air con	


Tyre Tread Depths

OSF	4.0	**OSR**	3.0	**NSF**	4.0	**NSR**	4.0
Spare		**Type**				**Run Flats**	0

Damage Details




1	**Seat Base Cover osr**	Soiled Light	Clean
2	**Seat Base Cover nsr**	Soiled Light	Clean
3	**Door Moulding osf**	Scuffed (Unpainted) UpTo 100mm	Smart Repair
4	**Door nsf**	Chipped Edge Chip	Smart Repair
5	**Wheel Trim nsr**	Missing Replace	Replace
6	**Wheel Trim osr**	Missing Replace	Replace
7	**Roof**	Scratched UpTo 25mm Not Thru Paint	Machine Polish
8	**Wheel Trim nsf**	Missing Replace	Replace
9	**Wheel Trim osf**	Scratched Over 50mm	Smart Repair
10	**Bonnet**	Scratched Over 25mm Thru Paint	Refinish
11	**Door osf**	Chipped Edge Chip	Smart Repair
12	**Bumper Rear**	Dented Between 10mm + 30mm	Smart Repair
	Bumper Rear	Previous Repair	Report Only
13	**Bumper Rear**	Scratched Over 25mm Not Thru Paint	Report Only
14	**Seat Base Cover osf**	Soiled Light	Clean
15	**Qtr Panel osr**	Chipped 1 To 5	Smart Repair





Sectional Damage Summary





16	**Seat Base Cover nsf**	Soiled Light	Clean
17	**Tailgate Pad**	Scuffed Over 25mm	Smart Repair
18	**Door nsr**	Dented 2 Or Less UpTo 10mm	Smart Repair
19	**Door nsr**	Scratched UpTo 25mm Not Thru Paint	Report Only

Damage Images

1  Seat Base Cover osr	2  Seat Base Cover nsr	3  Door Moulding osf	4  Door nsf
5  Wheel Trim nsr	6  Wheel Trim osr	7  Roof	8  Wheel Trim nsf
9  Wheel Trim osf	10  Bonnet	11  Door osf	12  Bumper Rear

13  Bumper Rear	14  Seat Base Cover osf	15  Qtr Panel osr	16  Seat Base Cover nsf
17  Tailgate Pad	18  Door nsr	19  Door nsr	

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Interior	 OSR Interior	 Dashboard
 Boot			

Inspection Notes : 1x charging lead			
Conditions:	Wet	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	TW	**Date:**	23/10/2025