



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

PK72KMF - VOLKSWAGEN ID3 LIFE **NAMA** 3

VIN:	WVWZZZE1ZPP000729		**Engine No:**	EBJC	
Transmission:	Automatic	**Odometer:**	64130	**Reg Date:**	31/10/2022
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	BLUE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Parking sensors	Heated seats	AUX/USB	Radio/CD
Cruise control	Climate control	Sat nav	


Tyre Tread Depths

OSF	7.0	**OSR**	7.0	**NSF**	7.0	**NSR**	7.0
Spare		**Type**	None			**Run Flats**	0



Damage Details

1	**Wheel nsf**	Dented UpTo 30mm (Steel)	Smart Repair
2	**Wheel Trim nsf**	Scratched Over 50mm	Smart Repair
3	**Seat Back Cover nsr**	Soiled Light	Clean
4	**Seat Base Cover nsr**	Soiled Light	Clean
5	**Wheel Trim osf**	Scratched Over 50mm	Smart Repair
6	**Seat Base Cover nsf**	Soiled Light	Clean
7	**Qtr Panel nsr**	Scratched UpTo 25mm Thru Paint	Smart Repair
8	**Bumper Front**	Scratched Over 100mm Thru Paint	Refinish
9	**Door Mirror Assy nsf**	Scratched (Painted) Over 25mm Thru Paint	Smart Repair
10	**Wheel Trim nsr**	Scratched Over 50mm	Smart Repair
11	**Wheel Trim osr**	Scratched Up To 50mm	Smart Repair
12	**Door nsr**	Dented With Paint Damage	Repair and Refinish


Sectional Damage Summary



Damage Images

1  Wheel nsf	2  Wheel Trim nsf	3  Seat Back Cover nsr	4  Seat Base Cover nsr
5  Wheel Trim osf	6  Seat Base Cover nsf	7  Qtr Panel nsr	8  Bumper Front
9  Door Mirror Assy nsf	10  Wheel Trim nsr	11  Wheel Trim osr	12  Door nsr

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Additional	 Front Interior	 Load Area
 Rear Interior	 Dashboard		

Inspection Notes : No charging cable			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	MM	**Date:**	23/10/2025