



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

RY21LKE - FORD KUGA VIGNALE HEV **NAMA** 4

VIN:	WF0FXXWPMHMA38426		**Engine No:**	MA38426	
Transmission:	Automatic	**Odometer:**	38925	**Reg Date:**	10/08/2021
Fuel Type:	Hybrid/Electric	**Engine CC:**	2488	**Colour:**	GREY
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Heated windscreen	Heated seats
Leather or substitute	AUX/USB	Radio/CD	Cruise control
Climate control	Air con	Sat nav	


Tyre Tread Depths

OSF	7.0	**OSR**	5.0	**NSF**	7.0	**NSR**	3.0
Spare		**Type**	None			**Run Flats**	0

Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Moulding osf Wing**	Scratched (Painted) Over 25mm Thru Paint	Smart Repair
3	**Door osf**	Dented With Paint Damage	Repair and Refinish
4	**Bumper Rear**	Dented Over 30mm	Repair and Refinish
5	**Qtr Panel Moulding os**	Broken Replace	Replace
	Screen Front	Chipped UpTo 10mm	Smart Repair
6	**Wing osf**	Poor Previous Repair Poor Paint	Refinish
7	**Door osr**	Dented Over 30mm	Repair and Refinish
8	**Tailgate Pad**	Scuffed Over 25mm	Smart Repair
9	**Bumper Rear Moulding**	Scratched (Painted) Over 25mm Thru Paint	Smart Repair

Sectional Damage Summary



Damage Images

1

Wheel nsf

2

Moulding osf Wing

3

Door osf

3

Door osf

4

Bumper Rear

5

Qtr Panel Moulding os

6

Wing osf

7

Door osr

7

Door osr

8

Tailgate Pad

9

Bumper Rear Moulding

Beauty Images


OSF


NSF


OSR


NSR


Speedometer


Additional


Dashboard


Front Interior


Rear Interior


Load Area

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	20/10/2025