



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

SC17SFF - FIAT 500 LOUNGE **NAMA** 4

VIN:	ZFA3120000J769823		**Engine No:**	2060737	
Transmission:	Manual	**Odometer:**	31828	**Reg Date:**	13/06/2017
Fuel Type:	Petrol	**Engine CC:**	1242	**Colour:**	BLACK
Body:	Hatchback	**Seats:**	4	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Panoramic roof	Leather or substitute
AUX/USB	Radio/CD	Cruise control	Air con


Tyre Tread Depths

OSF	6.0	**OSR**	5.0	**NSF**	6.0	**NSR**	5.0
Spare		**Type**	None			**Run Flats**	0


Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Wheel osf**	Scratched Over 50mm	Smart Repair
3	**Roof**	Chipped Multiple Chips	Refinish
4	**Bumper Rear**	Cracked Over 25mm	Replace
5	**Qtr Panel nsr**	Scratched Over 25mm Thru Paint	Refinish
6	**Wing osf**	Dented With Paint Damage	Repair and Refinish
7	**Door nsf**	Scratched Over 25mm Thru Paint	Refinish
8	**Bumper Front**	Scratched Over 100mm Thru Paint	Refinish

Sectional Damage Summary



Damage Images

1

Wheel nsf

2

Wheel osf

3


Roof

4

Bumper Rear

5

Qtr Panel nsr

6

Wing osf

7

Door nsf

8

Bumper Front

8

Bumper Front

Beauty Images


OSF


NSF



OSR


NSR


Speedometer


Front Interior


Load Area


Rear Interior


Dashboard

Inspection Notes : Can't open tailgate			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	MM	**Date:**	23/10/2025