



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

SM70XDL - NISSAN LEAF ACENTA **NAMA** 5

VIN:	SJNFAAZE1U0112294		**Engine No:**	319432Z	
Transmission:	Automatic	**Odometer:**	51055	**Reg Date:**	09/02/2021
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	WHITE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	AUX/USB	Radio/CD	Cruise control
Climate control	Air con	Sat nav	


Tyre Tread Depths

OSF	4.0	**OSR**	6.0	**NSF**	4.0	**NSR**	5.0
Spare		**Type**	None			**Run Flats**	0

Damage Details


1	**Carpets Front**	Holed Over 3mm	Replace
2	**Seat Base Cover osr**	Soiled Light	Clean
	Wheel nsr	Scratched Over 50mm	Smart Repair
3	**Wing osf**	Poor Previous Repair Rippled UpTo 30%	Repair and Refinish
4	**Door nsf**	Dented Over 30mm	Repair and Refinish
5	**Wheel nsf**	Scratched Over 50mm	Smart Repair
6	**Wheel osf**	Scratched Over 50mm	Smart Repair
7	**Fascia Trim**	Damaged Replace	Replace
8	**Roof**	Dented Between 10mm + 30mm	Smart Repair
9	**Bonnet**	Dented Over 2 UpTo 10mm	Smart Repair
10	**Door osf**	Dented Over 30mm	Repair and Refinish
11	**Bumper Rear**	Poor Previous Repair Poor Paint	Refinish
12	**Qtr Panel nsr**	Dented Over 30mm	Repair and Refinish
	B Post ns	Scratched UpTo 25mm Thru Paint	Smart Repair
13	**Seat Base Cover nsf**	Soiled Light	Clean
14	**Screen Front**	Chipped UpTo 10mm	Smart Repair

Sectional Damage Summary




15	**Door osr**	Dented Between 10mm + 30mm	Smart Repair
16	**Tailgate Pad**	Scuffed Over 25mm	Smart Repair
17	**Sill ns**	Scratched UpTo 25mm Thru Paint	Smart Repair
18	**Aperture Seal osf**	Broken Replace	Replace
19	**Sill os**	Scratched UpTo 25mm Thru Paint	Smart Repair
20	**Bumper Front**	Poor Previous Repair Poor Paint	Refinish
21	**Door nsr**	Poor Previous Repair Rippled UpTo 30%	Repair and Refinish

Damage Images

1

Carpets Front

2

Seat Base Cover osr

3

Wing osf

4

Door nsf

5

Wheel nsf

6


Wheel osf

7



Fascia Trim

8

Roof

9  Bonnet	10  Door osf	11  Bumper Rear	12  Qtr Panel nsr
13  Seat Base Cover nsf	14  Screen Front	15  Door osr	16  Tailgate Pad
17  Sill ns	18  Aperture Seal osf	19  Sill os	20  Bumper Front
21  Door nsr			

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Front Interior	 Rear Interior
 Load Area	 Additional		

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford

Inspector's Name:	RK	Date:	16/10/2025