



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

ST65AUR - SEAT MII BY MANGO **NAMA** 2

VIN:	VSSZZZAAZGD305937		**Engine No:**	CHYB891069	
Transmission:	Manual	**Odometer:**	56778	**Reg Date:**	10/10/2015
Fuel Type:	Petrol	**Engine CC:**	999	**Colour:**	BEIGE
Body:	Hatchback	**Seats:**	4	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Leather or substitute	Radio/CD
Air con			


Tyre Tread Depths

OSF	3.0	**OSR**	5.0	**NSF**	4.0	**NSR**	4.0
Spare		**Type**	None			**Run Flats**	0


Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Roof**	Dented Between 10mm + 30mm	Smart Repair
3	**Roof**	Scratched Over 25mm Not Thru Paint	Report Only
4	**Roof**	Previous Repair	Report Only
5	**Bonnet**	Dented With Paint Damage	Repair and Refinish
6	**Wheel nsr**	Scratched Over 50mm	Smart Repair
	Qtr Panel nsr	Scratched UpTo 25mm Thru Paint	Smart Repair
	Qtr Panel nsr	Previous Repair	Report Only
	Screen Front	Chipped UpTo 10mm	Smart Repair
	Door nsf	Dented 2 Or Less UpTo 10mm	Smart Repair
	Door nsf	Dented 2 Or Less UpTo 10mm	Report Only

Sectional Damage Summary



Damage Images

1

Wheel nsf

2

Roof

3

Roof

4

Roof

5

Bonnet

6

Wheel nsr

Beauty Images


OSF


NSF



OSR



NSR


Speedometer


Interior


Load Area


OSR Interior


Dashboard

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	21/10/2025