



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

WB19MVR - VAUXHALL GRANDLAND X **NAMA** 4

VIN:	W0VZRHNS1KS057021		**Engine No:**	10XVAW1319184 LES	
Transmission:	Manual	**Odometer:**	75313	**Reg Date:**	31/07/2019
Fuel Type:	Petrol	**Engine CC:**	1199	**Colour:**	WHITE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Air con	Sat nav


Tyre Tread Depths

OSF	3.0	**OSR**	5.0	**NSF**	5.0	**NSR**	4.0
Spare		**Type**	Space Saver			**Run Flats**	0


Damage Details

1	**Moulding osf Wing**	Scuffed (Unpainted) UpTo 100mm	Smart Repair
2	**General Interior**	Soiled Light	Clean
3	**C Post os**	Scratched UpTo 25mm Thru Paint	Smart Repair
4	**Door osf**	Scratched Over 25mm Not Thru Paint	Machine Polish
5	**Bumper Rear**	Scratched 25 to 100mm Thru Paint	Smart Repair
	Wheel nsr	Scratched Up To 50mm	Smart Repair
6	**Door osr**	Scratched Over 25mm Not Thru Paint	Machine Polish
7	**Screen Front**	Cracked Replace	Replace
	Door nsf	Dented 2 Or Less UpTo 10mm	Smart Repair
8	**Bumper Front Moulding**	Scuffed (Unpainted) UpTo 100mm	Smart Repair
9	**Bumper Front**	Cracked Over 25mm	Replace
	Door Mirror Assy nsf	Scratched (Painted) Over 25mm Not Thru Paint	Machine Polish
	Door nsr	Dented Between 10mm + 30mm	Smart Repair
	Door nsr	Previous Repair	Report Only

Sectional Damage Summary




Damage Images

1

Moulding osf Wing


2

General Interior

2

General Interior

3

C Post os


4

Door osf

5

Bumper Rear

6

Door osr

7

Screen Front

8

Bumper Front Moulding

9

Bumper Front

Beauty Images


OSF



NSF


OSR



NSR


Dashboard


Additional


Interior


Load Area


OSR Interior


Additional

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	22/10/2025