



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

WJ20XRM - MERCEDES-BENZ A 200 **NAMA** 1

VIN:	W1K1770872N157007		**Engine No:**	28291480344653	
Transmission:	Manual	**Odometer:**	20161	**Reg Date:**	13/03/2020
Fuel Type:	Petrol	**Engine CC:**	1332	**Colour:**	BLACK
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Heated seats	Leather or substitute
AUX/USB	Radio/CD	Cruise control	Climate control
Air con	Sat nav		


Tyre Tread Depths

OSF	7.0	**OSR**	7.0	**NSF**	7.0	**NSR**	7.0
Spare		**Type**	Inflation Kit			**Run Flats**	0



Damage Details

1	**Roof**	Scratched Over 25mm Not Thru Paint	Machine Polish
2	**Bonnet**	Chipped 1 To 5	Smart Repair
	Qtr Panel osr	Previous Repair	Report Only
	Door osr	Previous Repair	Report Only
3	**Wing osf**	Chipped 1 To 5	Smart Repair
4	**Wing nsf**	Scratched Over 25mm Not Thru Paint	Machine Polish



Sectional Damage Summary



Damage Images

1  Roof	2  Bonnet	3  Wing osf	4  Wing nsf

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Interior	 Load Area
 OSR Interior			

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	29/09/2025