



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

WO19BJU - JEEP COMPASS **NAMA** 3

VIN:	MCANJPBH2JFA37028		**Engine No:**	2474100	
Transmission:	Manual	**Odometer:**	48536	**Reg Date:**	25/05/2019
Fuel Type:	Petrol	**Engine CC:**	1368	**Colour:**	WHITE
Body:	Estate	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Leather or substitute	AUX/USB
Radio/CD	Cruise control	Climate control	Sat nav


Tyre Tread Depths

OSF	4.0	**OSR**	7.0	**NSF**	7.0	**NSR**	2.0
Spare		**Type**	Inflation Kit			**Run Flats**	0


Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Carpets Front**	Scuffed Over 25mm	Smart Repair
3	**C Post os**	Scratched UpTo 25mm Thru Paint	Smart Repair
4	**Shelfload Cover Rear**	Missing Replace	Replace
5	**Bumper Rear**	Scratched Over 100mm Thru Paint	Refinish
6	**Door nsf**	Poor Previous Repair Rippled Over 30%	Repair and Refinish
7	**C Post ns**	Scratched UpTo 25mm Thru Paint	Smart Repair
8	**Roof Lining**	Torn UpTo 3mm	Smart Repair
9	**Rear Panel Trim Int**	Soiled Light	Clean
10	**Door nsr**	Poor Previous Repair Rippled Over 30%	Repair and Refinish

Sectional Damage Summary



Damage Images

1

Wheel nsf

2

Carpets Front

3

C Post os

4

Shelfload Cover Rear

5

Bumper Rear

5

Bumper Rear

6

Door nsf

6

Door nsf

6

Door nsf

7

C Post ns

8

Roof Lining

9

Rear Panel Trim Int

9

Rear Panel Trim Int

10

Door nsr

Beauty Images


OSF



NSF


OSR


NSR


Dashboard


Additional


Front Interior


Load Area


Rear Interior

Inspection Notes :			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	MM	**Date:**	08/10/2025