



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

YE15HGA - SMART FORFOUR PASSION **NAMA** 4

VIN:	WME4530422Y031846		**Engine No:**	H4DA400U114053	
Transmission:	Manual	**Odometer:**	99845	**Reg Date:**	31/07/2015
Fuel Type:	Petrol	**Engine CC:**	999	**Colour:**	BLACK
Body:	Hatchback	**Seats:**	4	**Spare Keys:**	1

Key Specification

Alloys	Radio/CD	Cruise control	Air con


Tyre Tread Depths

OSF	4.0	**OSR**	3.0	**NSF**	5.0	**NSR**	6.0
Spare		**Type**	Inflation Kit			**Run Flats**	0

Damage Details


1	**Carpets Front**	Scuffed Over 25mm	Smart Repair
2	**Carpets Front**	Soiled Light	Report Only
3	**Seat Base Cover nsr**	Soiled Light	Clean
4	**Wheel nsr**	Scratched Over 50mm	Smart Repair
5	**Door nsf**	Dented Over 30mm	Repair and Refinish
6	**Wheel nsf**	Scratched Over 50mm	Smart Repair
7	**Wheel osf**	Scratched Over 50mm	Smart Repair
8	**Door osf**	Scratched Over 25mm Thru Paint	Refinish
9	**Bumper Rear**	Cracked Over 25mm	Replace
10	**B Post os**	Scratched UpTo 25mm Thru Paint	Smart Repair
11	**Seat Base Cover osf**	Soiled Light	Clean
12	**Seat Base Cover nsf**	Soiled Light	Clean
13	**Screen Front**	Cracked Replace	Replace
14	**Door osr**	Scratched Over 25mm Thru Paint	Refinish
15	**Door Pad osf**	Burn Over 10mm	Replace
16	**Bumper Rear Moulding**	Broken Replace	Replace

Sectional Damage Summary




17	**Door nsr**	Dented 2 Or Less UpTo 10mm	Smart Repair

Damage Images

1  Carpets Front	2  Carpets Front	3  Seat Base Cover nsr	4  Wheel nsr
5  Door nsf	6  Wheel nsf	7  Wheel osf	8  Door osf
9  Bumper Rear	10  B Post os	11  Seat Base Cover osf	12  Seat Base Cover nsf
13  Screen Front	14  Door osr	15  Door Pad osf	16  Bumper Rear Moulding

17



Door nsr

Beauty Images



OSF



NSF




OSR




NSR



Speedometer



Dashboard



Front Interior



Rear Interior



Load Area

Inspection Notes : D			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	23/10/2025