



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

YN22UBF - MERCEDES-BENZ CLA 200 **NAMA** 3

VIN:	W1K1186872N292326		**Engine No:**	28291480782668	
Transmission:	Automatic	**Odometer:**	33224	**Reg Date:**	29/03/2022
Fuel Type:	Petrol	**Engine CC:**	1332	**Colour:**	GREY
Body:	Estate	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	Heated seats	Leather or substitute
AUX/USB	Radio/CD	Cruise control	Climate control
Air con	Sat nav		


Tyre Tread Depths

OSF	4.0	**OSR**	6.0	**NSF**	5.0	**NSR**	5.0
Spare		**Type**	None			**Run Flats**	0

Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Wheel nsr**	Scratched Over 50mm	Smart Repair
	Qtr Panel osr	Dented 2 Or Less UpTo 10mm	Smart Repair
3	**B Post os**	Dented 2 Or Less UpTo 10mm	Smart Repair
4	**A Post os**	Scratched UpTo 25mm Thru Paint	Smart Repair
5	**Sill os**	Dented With Paint Damage	Repair and Refinish
6	**Bumper Front**	Scratched Over 100mm Thru Paint	Refinish
7	**Bumper Front**	Previous Repair	Report Only
8	**Roof Lining**	Holed UpTo 3mm	Smart Repair


Sectional Damage Summary



Damage Images

1  Wheel nsf	2  Wheel nsr	3  B Post os	4  A Post os
5  Sill os	6  Bumper Front	7  Bumper Front	8  Roof Lining

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Front Interior	 Rear Interior
 Load Area			

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	15/10/2025