



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

YP69NNU - MERCEDES-BENZ EVITO **NAMA** 4

VIN:	WDF44760323570667		**Engine No:**	78070130000586	
Transmission:	Automatic	**Odometer:**	36869	**Reg Date:**	25/10/2019
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	BLUE
Body:	Other	**Seats:**	3	**Spare Keys:**	1

Key Specification

AUX/USB	Radio/CD	Air con	Sat nav


Tyre Tread Depths

OSF	5.0	**OSR**	6.0	**NSF**	6.0	**NSR**	6.0
Spare		**Type**	None			**Run Flats**	0

Damage Details

1	**General Interior**	Soiled Light	Clean
2	**Wing nsf**	Poor Previous Repair Poor Paint	Refinish
3	**Door nsf**	Dented Between 10mm + 30mm	Smart Repair
4	**Door Mirror Assy osf**	Scuffed (Unpainted) Over 100mm	Smart Repair
5	**Door Mirror Assy nsf**	Scuffed (Unpainted) Over 100mm	Smart Repair
	Wheel Trim nsr	Scratched Over 50mm	Smart Repair
	Wheel Trim osr	Scratched Over 50mm	Smart Repair
6	**Wheel Trim nsf**	Broken Replace	Replace
7	**General Exterior**	Decals Fitted Body Transfers	Report Only
	Bonnet	Scratched Over 25mm Not Thru Paint	Machine Polish
	Wheel Trim osf	Scratched Up To 50mm	Smart Repair
8	**Door osf**	Dented Between 10mm + 30mm	Smart Repair
9	**Tailgate**	Dented Between 10mm + 30mm	Smart Repair
10	**Qtr Panel osr**	Poor Previous Repair Rippled UpTo 30%	Repair and Refinish
	Qtr Panel nsr	Dented Between 10mm + 30mm	Smart Repair
11	**Door osr**	Poor Previous Repair Rippled Over 30%	Repair and Refinish

Sectional Damage Summary




12	**Bumper Front**	Poor Previous Repair Poor Paint	Refinish
	Bumper Front	Chipped 1 To 5	Report Only
13	**Door nsr**	Dented Over 30mm	Repair and Refinish

Damage Images

1

General Interior

2

Wing nsf

3

Door nsf

4

Door Mirror Assy osf

5

Door Mirror Assy nsf

6


Wheel Trim nsf

7

General Exterior

8

Door osf

9

Tailgate

10

Qtr Panel osr

11

Door osr

12

Bumper Front

12



Bumper Front

13



Door nsr

Beauty Images



OSF



NSF



OSR




NSR



Dashboard



Additional



Interior



Load Area



OSR Interior

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	17/10/2025