





Service Bulletin

MAKE YOU UP TO DATE WITH THE LATEST NEWS FROM FRANK MOHN SERVICES AS

UPGRADED FRAMO STRIPPING / PURGING VALVE



- Cargopump with the old design stripping/purging valve



-New design

ADVANTAGES:

Latest design acc. to class requirements

Easier trouble shooting

Full segregation between cargo / cofferdam

Favourable price

Reduced maintenance costs

Fully interchangeable






DEAR FRAMO - CUSTOMER

In this service bulletin we wish to draw your attention to the importance of purging the cargo pumps. As you will know this is the only way to check for leakages and it is absolutely necessary that the purging is carried out as described in the instruction book.

By purging as instructed you will at once discover if there is any leakages in the pump, and you are able to determine if it is cargo or hydraulic oil - or both ! - and if it is a static or dynamic leak. The result will tell you what action that is necessary to take - and such action must be taken at once on board the ship. As an extra precaution we do recommend that the purging routine forms are filled in and sent to us. We will, as a free service, go through these and give written comments.



**Upgraded stripping/purging valves
drg.no.264-363-2 & 293-514-2**

On older FRAMO cargo pumps there is a combined purging and stripping valve. On newer pumps we have supplied two completely separate valves.

We have now also developed a modified valve, with complete segregation between cargo and cofferdam, which can be installed on older pumps, where the combined valve originally is used.

We are pleased to present the new upgraded FRAMO stripping and purging valves for the FRAMO cargo pump, our drg. no. 264-363-2 and 293-514-2. This modification is carried out according to the latest FRAMO design on new hydr. systems and class requirements. The drg. no. 264-363-2 replaces old design valve drg. no. 264-117-2 and drg. no. 293-514-2 replaces old design valve drg. no. 269-436-2.

THE ADVANTAGES BETWEEN THE OLD AND NEW DESIGN CAN BE SUMMARIZED AS FOLLOWS:

- easy operation
- the new design is almost maintenance free, due to less o-rings and seals.
- Full segregation between cargo and cofferdam. (Class requirements):
- favourable price !
(Please contact our spares dept. for a price offer).
- fully interchangeable with the old design.

To get a long and trouble free operation of the FRAMO system stripping and regular purging is some of the most important functions of the FRAMO system.



STRIPPING PROCEDURE:

- To minimize the slop in the cargo (ref. service bulletin no. 3 - 1990).

PURGING PROCEDURE:

- The purging must be carried out according to FRAMO purging procedures in order to follow up the condition of the cargo and oil seals.
- This will give you a good picture if you have dynamic leakage (during discharge) or a static leakage (during voyage) and if any action must be taken.
- We will at any time be delighted to give you our recommendations for appropriate action.

PURGING HOSE:


We will also be able to supply you with a purging hose with quick couplings.

We would be very pleased if you contacted one of our offices abroad or Frank Mohn Services AS for a price quotation.


We are sure that you will find the price interesting.

Yours faithfully
pr. Frank Mohn Services AS

Bjørn H. Johnsen
Bjørn H. Johnsen



Old design stripping/purging valve fitted on topcover plate.



Upgraded stripping/purging valve fitted on topcover plate.



Frank Mohn Services AS

Head office: Frank Mohn AS, P.O.Box 98 Slåtthaug, 5851 Bergen, Norway, Phone: +47 55 99 90 00, Telefax: +47 55 99 93 80

Frank Mohn Flatøy AS, Flatøy, 5918 Frekhaug, Norway, Phone: +47 55 99 94 00, Telefax: +47 55 99 95 81

Frank Mohn Fusa AS, P.O.Box 10, 5641 Fusa, Norway, Phone: +47 55 99 96 00, Telefax: +47 55 99 97 80

Frank Mohn Services AS, P.O.Box 44 Slåtthaug, 5851 Bergen, Norway, Phone: +47 55 99 92 00, Telefax: +47 55 99 93 82

Framo Engineering AS, P.O.Box 174 Sandsli, 5862 Bergen, Norway, Phone: +47 55 92 88 00, Telefax: +47 55 92 89 00

Frank Mohn Nederland BV, Edisonweg 18, P.O.Box 305, 3200 AH Spijkenisse, The Netherlands, Phone: +31 181 619311, Telefax: +31 181 611193

Frank Mohn Houston Inc, 1802 West D Street, La Porte, Texas 77571-4601, USA, Phone: +1 281 471 7920, Telefax: +1 281 470 1258

Frank Mohn Singapore Pte Ltd, 17 Tuas View, Circuit Singapore 637575, Phone: +65 861 4455, Telefax: +65 861 5910

Frank Mohn AS Sweden Office, Askims Industriväg 1 A, 43634 Askim, Sweden, Phone: +46 31 682085, Telefax: +46 31 681048

Frank Mohn Nippon K.K., City-haz Chojamachi Building 6 - 3, Chojamachi 2-chome, Naka-Ku, Yokohama 231-0033, Japan, Phone: +81 45 253 7155, Telefax: +81 45 253 7188

Frank Mohn Korea Office, Rm. 309, Yachting Center Bldg., 1393, Woo-1Dong, Haeundae-Ku, Pusan, Korea, Phone: +82 51 743 6942, Telefax: +82 51 743 6944

Frank Mohn China Ltd, Unit 804A, Pine City, 8 Dong An Road, Shanghai 200032, China, Phone: +86 21 6443 8845, Telefax: +86 21 6443 8846

Frank Mohn do Brasil Ltda, Av. Presidente Wilson, 231/15º Andar, 20031-021 - Rio de Janeiro - RJ, Brazil, Phone: +55 21 2544 2040, Telefax: +55 21 2544 2041