AI Car Damage Inspection Report


Report ID: d3387c1a-7ce | **Timestamp:** 2026-11-02 09:34:33 UTC

Inspection Verdict	DAMAGED	**Confidence Score**	98.5%
Estimated Severity	SEVERE	**Damaged Area Ratio**	20.72%
Needs Human Review	NO (Auto Pass)	**Pipeline Latency**	79.7 ms

Visual Inspection (Original vs. AI Annotated Detections)



Original Vehicle Photo



Annotated Damage Localization (YOLO11)

Localized Damage Regions

#	Damage Class	Confidence	Bounding Box [x1, y1, x2, y2]
1	severe_replace	95.6%	[131.0, 234.7, 535.2, 367.8]
2	dent	50.3%	[143.2, 239.2, 255.4, 357.4]
3	dent	33.3%	[509.7, 231.2, 539.8, 268.2]
4	dent	32.7%	[140.3, 251.3, 220.4, 313.8]
5	dent	31.2%	[439.7, 178.9, 545.9, 271.2]

Disclaimer: This report was generated automatically by the AI Car Damage Inspection System (ConvNeXt-Tiny Classifier + YOLO11 Detector + Calibrated Severity Heuristic). Severity scores are calibrated estimates for insurance claims triage and rental return checks, not a certified structural repair quote.