

## TREE-RING RECONSTRUCTED DROUGHT GRID POINT: 105 110.0W 32.5N



## **CALIBRATION & VERIFICATION STATISTICS**



CRSQ, VRSQ < 0.1 = p < 0.05

RE,CE < 0.0 = no skill