





impure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



impure 11_12 — halves could not be aligned — shown as measured





impure 11_21 — halves could not be aligned — shown as measured





impure 11_22 — halves could not be aligned — shown as measured



impure 12_13 — halves could not be aligned — shown as measured



impure 12_21 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

impure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



impure 12_22 — halves could not be aligned — shown as measured





impure 12_23 — halves could not be aligned — shown as measured





impure 13_14 — aligned: $-V \approx \pm(+V)(1.12 \cdot w - 312)$, $r=0.86$



impure 13_22 — halves could not be aligned — shown as measured



impure 13_23 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

impure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



impure 13_24 — halves could not be aligned — shown as measured





impure 14_23 — aligned: $-V \approx \pm(+V)(0.92 \cdot w + 384)$, $r=0.96$





impure 14_24 — aligned: $-V \approx \pm(+V)(0.96 \cdot w + 240)$, $r=0.90$



impure 21_22 — aligned: $-V \approx \pm(+V)(0.95 \cdot w + 264)$, $r=0.97$



impure 21_31 — aligned: $-V \approx \pm(+V)(1.02 \cdot w + 104)$, $r=0.86$





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

impure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



impure 21_32 — aligned: $-V \approx \pm(+V)(1.01 \cdot w + 296)$, $r=0.97$





impure 22_23 — aligned: $-V \approx \pm(+V)(0.93 \cdot w + 264)$, $r=0.84$





impure 22_31 — aligned: $-V \approx \pm(+V)(0.93 \cdot w + 360)$, $r=0.85$



impure 22_32 — aligned: $-V \approx \pm(+V)(0.94 \cdot w + 368)$, $r=0.93$





impure 22_33 — aligned: $-V \approx \pm(+V)(1.07 \cdot w + 376)$, $r=0.90$




impure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



impure 23_24 — halves could not be aligned — shown as measured





impure 23_32 — aligned: $-V \approx \pm(+V)(0.99 \cdot w + 272)$, $r=0.99$





impure 23_33 — aligned: $-V \approx \pm(+V)(0.98 \cdot w + 328)$, $r=0.95$



impure 23_34 — halves could not be aligned — shown as measured



impure 24_33 — aligned: $-V \approx \pm(+V)(1.14 \cdot w + 96)$, $r=0.84$





Wavenumber, common axis (cm^{-1})



Wavenumber, common axis (cm^{-1})

impure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



impure 24_34 — halves could not be aligned — shown as measured





impure 31_32 — halves could not be aligned — shown as measured





impure 31_41 — aligned: $-V \approx \pm(+V)(1.00 \cdot w + 392)$, $r=0.96$



impure 31_42 — aligned: $-V \approx \pm(+V)(1.10 \cdot w + 32)$, $r=0.96$



impure 32_33 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

impure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



impure 33_43 — halves could not be aligned — shown as measured





impure 33_44 — halves could not be aligned — shown as measured





impure 34_43 — halves could not be aligned — shown as measured



impure 34_44 — halves could not be aligned — shown as measured



impure 41_42 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm^{-1})



Wavenumber, common axis (cm^{-1})

impure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



impure 41_51 — aligned: $-V \approx \pm(+V)(0.95 \cdot w + 136)$, $r=0.92$





impure 41_52 — halves could not be aligned — shown as measured





impure 42_43 — halves could not be aligned — shown as measured



impure 42_51 — halves could not be aligned — shown as measured



impure 42_52 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

impure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



impure 42_53 — halves could not be aligned — shown as measured





impure 43_44 — aligned: $-V \approx \pm(+V)(1.05 \cdot w + 208)$, $r=0.95$





impure 43_52 — aligned: $-V \approx \pm(+V)(1.06 \cdot w + 208)$, $r=0.94$



impure 43_53 — aligned: $-V \approx \pm(+V)(0.93 \cdot w + 216)$, $r=0.96$



impure 43_54 — aligned: $-V \approx \pm(+V)(1.01 \cdot w + 296)$, $r=0.95$





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

impure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



impure 44_53 — halves could not be aligned — shown as measured





impure 44_54 — aligned: $-V \approx \pm(+V)(1.10 \cdot w + 360)$, $r=0.92$





impure 51_52 — halves could not be aligned — shown as measured



impure 52_53 — aligned: $-V \approx \pm(+V)(0.89 \cdot w + 248)$, $r=0.95$



impure 53_54 — aligned: $-V \approx \pm(+V)(0.89 \cdot w + 280)$, $r=0.95$ [nearly identical data in both device folders]



Wavenumber, common axis (cm⁻¹)

Wavenumber, common axis (cm⁻¹)