

Food safety complaint - evidence package

Prepared by SATVA · Reference SATVA-2026-DEMO01 · Generated 04 September 2026, 16:00 IST

What this document is. SATVA is a screening aid. It is not a statutory test, a certification, or a legal determination of food safety. A visual screening result is advisory only and must never be treated as proof of adulteration. Only a confirmatory colorimetric strip reading may be escalated, and escalation is routed to the statutory FSSAI channel rather than replacing it.

This complaint has NOT been submitted. SATVA does not file complaints on anyone's behalf. Attach this document to a complaint you raise yourself through FSSAI Food Safety Connect or your State Food Safety Department. Filing instructions are on the last page.

1. Confirmatory chemical reading

This is the quantitative result of a colorimetric test strip read against a printed reference card. It is the only measurement in this package that SATVA treats as evidence.

Test performed	Turmeric indicator - carbide residue
Result	5.17 mg/L equivalent (indicative)
Confidence interval	4.47 to 5.87 mg/L equivalent (indicative)
Interpretation band	Strong
Action threshold	1 mg/L equivalent (indicative)
Exceeds action threshold	Yes - the lower bound of the confidence interval is at or above the action threshold
Calibration series	turmeric-carbide-v1
Laboratory validated	No - see the limitations note below

Limitation the reader must weigh. The calibration series used for this reading has not yet been validated against a NABL-accredited laboratory. The measurement is reproducible and was taken under verified capture conditions, but it should be treated as grounds for drawing an official sample, not as a substitute for laboratory analysis.

2. Time and place

Date and time of purchase or sampling	04 September 2026, 14:45 IST
GPS coordinates	10.775712, 76.654830 (GPS accuracy approximately 8 m)
Ward	Palakkad Ward 14 (PKD-14)
District	Palakkad
State	Kerala
Place description	Fruit stall near the municipal market entrance
Commodity	Mango
Variety	Banganapalli

3. Food business operator

Name as given by complainant (demo data) Stall 12, Municipal Market

Address	Municipal Market Rd, Palakkad
FSSAI licence / registration	Not known

4. Complainant

Name	A. Consumer
Phone	+91-9XXXXXXXXX
Email	-

5. Complainant's account

The fruit had uniform colour but the stem end was still green, which is what prompted the strip test.

6. Preliminary visual screening (advisory only)

An on-device image model returned an anomaly score of **78 out of 100** (model satva-screen-dev-0.1). **This score is not evidence.** It is a triage signal whose only purpose was to decide whether performing the chemical test in section 1 was worthwhile. The image model does not detect any chemical; it responds to visual characteristics associated with forced ripening. It must not be relied on as an indication that any offence occurred.


7. Traceability

Lot code	MNG-20260901-7F3A
Chain integrity	verified - the custody chain recomputes correctly from origin

Photographic evidence

Each image is listed with a SHA-256 digest computed when it was captured. The digest lets a recipient confirm that an image supplied separately is byte-for-byte the one referenced here.

Exhibit 1. The reacted test strip beside the SATVA reference card



Captured: 04 September 2026, 14:50 IST

SHA-256: 32a1987ec21632d530a92537659c024b25ab9da42ece307a07535cbe9f57f2bf

Measurement conditions

SATVA refuses to produce a reading when capture conditions fall outside validated limits, rather than reporting a low-confidence number. The reading in section 1 passed every check below.

Reference card detected	Yes
Colour correction residual	dE 0.57 mean across reference patches
Reference white level	238.4 / 255
Illuminant neutrality	chroma 1.8
Strip uniformity	L* standard deviation 1.2

How to file this complaint

1. Open the **FSSAI Food Safety Connect** mobile application, or visit <https://foodlicensing.fssai.gov.in/cmsweb/>, or contact your District Designated Officer or State Food Safety Department.
2. Raise a complaint under the food-safety category that matches this commodity.
3. Enter the date, time and location from section 2 of this document.
4. Attach this PDF together with the original photographs.
5. Quote SATVA reference **SATVA-2026-DEMO01** so the two records can be matched.
6. Retain the acknowledgement number the authority issues. You can record it in SATVA to keep this package linked to the official complaint.

A visual screening result on its own has never been treated as sufficient grounds for this package, and SATVA has no authority to determine that any food is unsafe or that any law has been broken. Only the food safety authority can draw an official sample, have it analysed by an accredited laboratory, and decide what action is warranted.