# 123 River Street


Exampleville, Ohio 43702

Owner Example, Pat
NFIP Community 399990 Exampleville, City of
Date of Assessment 09/21/2026

**Percent Damaged**
**75.0%**
**Substantially Damaged**

Basis for Value of Structure
**$129,189.26**
Computed Actual Cash Value

Basis for Cost of Repairs
**$96,900.46**
Computed Damages



## Structure Address

| | |
|---|---|
| Owner's Name | Example, Pat |
| Street Address | 123 River Street |
| City | Exampleville |
| County/Parish | Union |
| State | Ohio |
| Zip | 43702 |
| Phone | (555) 555-0142 |

## Structure Information

| | |
|---|---|
| Year of Construction | 1962 |
| Residence Type | Single Family Residence |
| Quality | Good |

## Subdivision

| | |
|---|---|
| Subdivision | Riverside Addition |
| Parcel # | 092-0004-0118-00 |
| Lot # | 18 |
| Elev. of Lowest Floor | 486.5 ft. |
| Datum | NAVD 88 |

## Community

| | |
|---|---|
| NFIP Community Name | Exampleville, City of |
| NFIP Community ID # | 399990 |
| Latitude | 39.098712 |
| Longitude | -84.507634 |

## Damage Information

| | | | |
|---|---|---|---|
| Date of Assessment | 09/21/2026 | Date of Damage | 09/14/2026 |
| Inspector Name | Inspector A | Cause of Damage | Flood |
| Inspector Phone | (555) 555-0100 | Duration of Flood | 2 Days |
| Residence Information | Brick ranch, attached one-car garage. | Est. Depth of Flood Above Lowest Floor | 4.25 |

## NFIP Information

| Firm Panel # | Suffix | Date of FIRM Panel | Firm Zone | BFE | Regulatory Floodway |
|---|---|---|---|---|---|
| 39061C0232 | E | 09/17/2010 | AE | 489.25 | No |

## Damage Summary

| | | | |
|---|---|---|---|
| Replacement Cost | $170,434.38 | Computed Damages | $96,900.46 |
| Depreciation % | 24.2% | Percent of Existing Improvements and Repairs Pre-Disaster | |
| Computed Actual Cash Value* | $129,189.26 | Repair/Reconstruction % | 75.0% |
| Other Depreciation Explanation | | | |

* Per FEMA Publication 213, Actual Cash Value may be used as Market Value.

## Optional User Entered Data

| | |
|---|---|
| Professional Market Appraisal | Contractor Estimate |
| Tax Assessed Value | Community Estimate |
| Factor Adjustment | |
| Adjusted Tax Assessed Value | |

**Authorized Local Official :** _____ Signature

**Authorized Local Official :** _____ Printed Name

# 400 Front Street


Exampleville, Ohio 43702-1234

Owner Riverside Holdings LLC
NFIP Community 399990 Exampleville, City of
Date of Assessment 09/22/2026

**Percent Damaged**
**51.6%**
**Substantially Damaged**

Basis for Value of Structure
**$1,271,911.80**
Computed Actual Cash Value

Basis for Cost of Repairs
**$656,876.72**
Computed Damages



## Structure Address

| | |
|---|---|
| Owner's Name | Riverside Holdings LLC |
| Street Address | 400 Front Street |
| City | Exampleville |
| County/Parish | Union |
| State | Ohio |
| Zip | 43702-1234 |
| Phone | |

## Structure Information

| | |
|---|---|
| Year of Construction | 1978 |
| Use | Office Building |
| Quality | Good |

## Subdivision

| | |
|---|---|
| Subdivision | |
| Parcel # | |
| Lot # | |
| Elev. of Lowest Floor | |
| Datum | |

## Community

| | |
|---|---|
| NFIP Community Name | Exampleville, City of |
| NFIP Community ID # | 399990 |
| Latitude | |
| Longitude | |

## Damage Information

| | | | |
|---|---|---|---|
| Date of Assessment | 09/22/2026 | Date of Damage | 09/14/2026 |
| Inspector Name | R. Inspector | Cause of Damage | Flood |
| Inspector Phone | | Duration of Flood | 3 Days |
| Structure Information | Three-story steel frame office. | Est. Depth of Flood Above Lowest Floor | 2.50 |

## NFIP Information

| Firm Panel # | Suffix | Date of FIRM Panel | Firm Zone | BFE | Regulatory Floodway |
|---|---|---|---|---|---|
| | | | | | |

## Damage Summary

| | | | |
|---|---|---|---|
| Replacement Cost | $1,851,400.00 | Computed Damages | $656,876.72 |
| Depreciation % | 31.3% | Percent of Existing Improvements and Repairs Pre-Disaster | |
| Computed Actual Cash Value* | $1,271,911.80 | Repair/Reconstruction % | 51.6% |
| Other Depreciation Explanation | | | |

* Per FEMA Publication 213, Actual Cash Value may be used as Market Value.

## Optional User Entered Data

| | |
|---|---|
| Professional Market Appraisal | Contractor Estimate |
| Tax Assessed Value | Community Estimate |
| Factor Adjustment | |
| Adjusted Tax Assessed Value | |

**Authorized Local Official :** _____ Signature

**Authorized Local Official :** _____ Printed Name

# 18 Mill Creek Street

Exampleville, Ohio 43702

Owner Rivera, Jordan
NFIP Community 399991 Union County Unincorporated Areas
Date of Assessment 09/23/2026

**Percent Damaged**

**32.1%**

**Not Substantially Damaged**

Basis for Value of Structure
**$129,189.26**
Computed Actual Cash Value

Basis for Cost of Repairs
**$41,449.64**
Computed Damages

No Photo Available

## Structure Address

| | |
|---|---|
| Owner's Name | Rivera, Jordan |
| Street Address | 18 Mill Creek Street |
| City | Exampleville |
| County/Parish | Union |
| State | Ohio |
| Zip | 43702 |
| Phone | |

## Structure Information

| | |
|---|---|
| Year of Construction | 1962 |
| Residence Type | Single Family Residence |
| Quality | Good |

## Subdivision

| | |
|---|---|
| Subdivision | |
| Parcel # | |
| Lot # | |
| Elev. of Lowest Floor | |
| Datum | |

## Community

| | |
|---|---|
| NFIP Community Name | Union County Unincorporated Areas |
| NFIP Community ID # | 399991 |
| Latitude | |
| Longitude | |

## Damage Information

| | | | |
|---|---|---|---|
| Date of Assessment | 09/23/2026 | Date of Damage | 09/14/2026 |
| Inspector Name | Inspector A | Cause of Damage | Flood |
| Inspector Phone | | Duration of Flood | 2 Days |
| Residence Information | | Est. Depth of Flood Above Lowest Floor | |

## NFIP Information

| Firm Panel # | Suffix | Date of FIRM Panel | Firm Zone | BFE | Regulatory Floodway |
|---|---|---|---|---|---|
| | | | | | |

## Damage Summary

| | | | |
|---|---|---|---|
| Replacement Cost | $170,434.38 | Computed Damages | $41,449.64 |
| Depreciation % | 24.2% | Percent of Existing Improvements and Repairs Pre-Disaster | |
| Computed Actual Cash Value* | $129,189.26 | Repair/Reconstruction % | 32.1% |
| Other Depreciation Explanation | | | |

* Per FEMA Publication 213, Actual Cash Value may be used as Market Value.

## Optional User Entered Data

| | |
|---|---|
| Professional Market Appraisal | Contractor Estimate |
| Tax Assessed Value | Community Estimate |
| Factor Adjustment | |
| Adjusted Tax Assessed Value | |

**Authorized Local Official :** _____ Signature

**Authorized Local Official :** _____ Printed Name

# 22 Mill Creek Street

Exampleville, Ohio 43702

Owner Lee, Sam
NFIP Community 399991 Union County Unincorporated Areas
Date of Assessment 10/20/2026

**Percent Damaged**
**0.0%**
**Resident Refused Inspection**

Basis for Value of Structure
**Not Provided**
Computed Actual Cash Value

Basis for Cost of Repairs
**$0.00**
Computed Damages

No Photo Available

## Structure Address

| | |
|---|---|
| Owner's Name | Lee, Sam |
| Street Address | 22 Mill Creek Street |
| City | Exampleville |
| County/Parish | |
| State | Ohio |
| Zip | 43702 |
| Phone | |

## Structure Information

| | |
|---|---|
| Year of Construction | 1962 |
| Residence Type | Single Family Residence |
| Quality | Good |

## Subdivision

| | |
|---|---|
| Subdivision | |
| Parcel # | |
| Lot # | |
| Elev. of Lowest Floor | |
| Datum | |

## Community

| | |
|---|---|
| NFIP Community Name | Union County Unincorporated Areas |
| NFIP Community ID # | 399991 |
| Latitude | |
| Longitude | |

## Damage Information

| | | | |
|---|---|---|---|
| Date of Assessment | 10/20/2026 | Date of Damage | 09/14/2026 |
| Inspector Name | Inspector A | Cause of Damage | Flood |
| Inspector Phone | | Duration of Flood | 2 Days |
| Residence Information | | Est. Depth of Flood Above Lowest Floor | |

## NFIP Information

| Firm Panel # | Suffix | Date of FIRM Panel | Firm Zone | BFE | Regulatory Floodway |
|---|---|---|---|---|---|
| | | | | | |

## Damage Summary

| | | | |
|---|---|---|---|
| Replacement Cost | $170,434.38 | Computed Damages | $96,900.46 |
| Depreciation % | 24.2% | Percent of Existing Improvements and Repairs Pre-Disaster | |
| Computed Actual Cash Value* | $129,189.26 | Repair/Reconstruction % | 75.0% |
| Other Depreciation Explanation | Owner declined entry; exterior inspection only. | | |

* Per FEMA Publication 213, Actual Cash Value may be used as Market Value.

## Optional User Entered Data

| | |
|---|---|
| Professional Market Appraisal | Contractor Estimate |
| Tax Assessed Value | Community Estimate |
| Factor Adjustment | |
| Adjusted Tax Assessed Value | |

**Authorized Local Official :** _____ Signature

**Authorized Local Official :** _____ Printed Name