

## KENYA RURAL ROADS AUTHORITY

Telephone:

Email Address: residenteng150@gmail.com

When replying please quote:

RESIDENT ENGINEER CHOGORIA - WERU ROAD PROJECT P.O. BOX 2718-60100 EMBU

Ref: KeRRA/16/1/LVSR/RWC150/RE-02/VOL.1/37A

Date: 11<sup>TH</sup> NOVEMBER, 2022

The Site Agent China Jiangxi I Kenya Ltd P.O. Box 31553 - 00600 NAIROBI

Dear Sir,

## <u>UPGRADING TO BITUMEN STANDARDS AND PERFORMANCE BASED ROUTINE</u> MAINTENANCE OF CHOGORIA WERU-KIRIANI ROAD; CONTRACT NO.RWC 150.

## REF: UNDEFINED DRAINAGE AND BLOCKED ACCESS CULVERTS

The above subject refers.

This office has noted with concern the high level of siltation on our drainage system due to the ongoing rains. This is in particular for the section at Km 3+200 L.H.S & R.H.S along the Marima-Kiriani road, where the culverts are completely silted and as a result, the water has overtopped the culverts and ended up in the adjacent residence making life unbearable for the occupants. (*Photos attached*)

Further to this, the drain before the culvert at Km 3+200 R.H.S is undefined resulting in rainwater crossing our road from the R.H.S to the L.H.S at that particular section.

You are therefore instructed;

- 1. To define the affected drains and channel the water to the culverts.
- 2. To open up all silted drains and blocked access culverts.

You also required to maintain the drainage system during the ongoing rains.


Kindly expedite to avoid further damages on adjacent land.

Yours faithfully,


Eng. P. M. Wachai.

RESIDENT ENGINEER

## BLOCKED DRAIN



KM.3+279 LHS



KM.3+200 RHS



KM.3+279

