Figure S7. Visualization of the mapping of the long-reads on the ESM015 and EP155 genome assemblies around the major detected synteny breaks.




Figure S7. Visualization of the mapping of the long-reads on the ESM015 and EP155 genome assemblies around the major detected synteny breaks.




Figure S7. Visualization of the mapping of the long-reads on the ESM015 and EP155 genome assemblies around the major detected synteny breaks.




Figure S7. Visualization of the mapping of the long-reads on the ESM015 and EP155 genome assemblies around the major detected synteny breaks.




Figure S7. Visualization of the mapping of the long-reads on the ESM015 and EP155 genome assemblies around the major detected synteny breaks.




Figure S7. Visualization of the mapping of the long-reads on the ESM015 and EP155 genome assemblies around the major detected synteny breaks.

1543121 1775927 2383767 2150857 232907 232911 99.87 3437609 3950794 6.77 5.90 ESM 6 scaffold 8 scaf




Figure S7. Visualization of the mapping of the long-reads on the ESM015 and EP155 genome assemblies around the major detected synteny breaks.




Figure S7. Visualization of the mapping of the long-reads on the ESM015 and EP155 genome assemblies around the major detected synteny breaks.

75387 93013 1423790 1406164 17627 17627 97.48 599387 5527719 2.94 0.32 ESM_11 scaffold 2 Major Intrascaffold Translocation ESM_11 — scaffold 2 115383 179603 591138 655400 64221 64263 98.97 599387 5527719 10.71 1.16 ESM_11 scaffold 2 Major Intrascaffold Translocation ESM_11 — scaffold 2




Figure S7. Visualization of the mapping of the long-reads on the ESM015 and EP155 genome assemblies around the major detected synteny breaks.

