



**Department of Social Justice & Empowerment GIGW
GUIDELINES
LEVEL – 1 TEST REPORT
FOR**

Ministry of Social Justice and Empowerment

**Prepared By
LEVITHAN TECHNOLOGIES PRIVATE LIMITED**

October 1, 2026

1. Management Summary

1.1 Document Title

DOCUMENT VERSION CONTROL	
Document Title	Department of Social Justice & Empowerment GIGW Guidelines Level – 1 Test Report
Organization Name	Ministry of Social Justice and Empowerment
Application Name	Web Application
Document Version	1.0
Job Received Date	September 30, 2026
Report No.	LTPL/MSJAE/DOSJNE/01
Last Edit Date	October 1, 2026

DOCUMENT SUBMISSION DETAILS	
Date	October 1, 2026
Classification	Confidential
Submitted To	Mr. Akash
Address	Shastri Bhawan, Dr. Rajendra Prasad Road, New Delhi, Delhi 110001
E-Mail	akashk@dewsolutions.in

1.2 Contact Details

Name	Mr. Varun Bansal
Designation	CEO
Company	Levithan Technologies Pvt. Ltd.
Address	205, 2 nd Floor, SSR Corporate Park, 13/6, NH-19, Sector 27B, Ekta Nagar, Faridabad, Haryana 121003
Mobile No.	+91 9718047400
E – Mail	varun.bansal@levithan.tech

Table of Contents

1. Management Summary	2
1.1 Document Title	2
1.2 Contact Details	2
2. Scope, Scan (Test) and Report (Creation/Review) Details	5
3. Assessment Constraints	6
4. Tools Used	6
5. Standard Followed	7
6. Guidelines	8
6.1 Quality Guidelines	8
6.2 Lifecycle Management Guidelines	10
6.3 Accessibility Guidelines	11
7. Summary of Key Findings	20
8. Detailed Technical Report with Recommendations	22
8.1 File Size and Format Information Not Provided	22
8.2 Archival Policy Not Provided for Required Documents	24
8.3 Contact Us Page Does Not Provide Complete Information	26
8.4 Feedback Page Not Available	27
8.5 Help Section Does Not Provide Sufficient Information	28
8.6 Chatbot Overlaps Content at Different Screen Sizes	29
8.7 Content Overlaps When CSS Is Disabled	31
8.8 Page Metadata Not Provided	32
8.9 Inconsistent Language Content on Web Pages	34
8.10 No Notification Provided for External Website Redirection	35
8.11 Content and Images Partially Visible During Printing	36
8.12 Web Information Manager (WIM) Not Identified	38
8.13 Website URL Not Displayed on Documents	39
8.14 WIM-Approved Policies and Plans Not Available	41
8.15 Alternative Text Missing for Non-Text Content	42
8.16 Captions Not Provided for Pre-Recorded Videos	44
8.17 H1 Heading Missing and Heading Sequence Improper	45
8.18 Insufficient Colour Contrast	47
8.19 Icons Overlap at 200% Text Resize	49
8.20 Table Header (<th>) Tag Missing	51
8.21 Content Cannot Be Properly Scrolled at 400% Zoom	52
8.22 Most Icons Are Not Keyboard Accessible	53
8.23 Icons Do Not Meet the Required Contrast Ratio	54
8.24 Keyboard Focus Disappears at the End of the Page	55
8.25 No Mechanism to Stop or Pause Moving Content	56
8.26 Link Information Is Not Properly Conveyed by Screen Reader	57
8.27 Labels Missing for Input Fields	59
8.28 Status Messages Are Not Properly Conveyed by Screen Reader	60

8.29 Some Content Is Not Properly Conveyed by Screen Reader	61
8.30 Error Identified in HTML and CSS Validation.....	62
9. General References	64

CONFIDENTIAL

2. Scope, Scan (Test) and Report (Creation/Review) Details

Following website is considered as scope of work during the assessment.

Scope of the work	
Name	Department of Social Justice & Empowerment
URL	https://www.dosje.gov.in/

Scan / Test Details	
Start Date	September 30, 2026
End Date	October 1, 2026
Scan / Test Time	2 Days

Report Created / Reviewed / Approved By	
Report Created By	Ms. Pranjal Sharma
Report Reviewed By	Mr. Gaurav Dutt Joshi
Report Approved By	Mr. Varun Bansal

3. Assessment Constraints

There were no assessment constraints in our audit.

4. Tools Used

The below tools/scans/scripts were used for audit:

- Web Developer Tool
- WAVE
- Colour Contrast Analyzer
- NVDA

5. Standard Followed

Below are the standards followed for GIGW Guidelines audit –

1. Guidelines for Indian Government Websites (GIGW)
2. Web Content Accessibility Guidelines (WCAG)

CONFIDENTIAL

6. Guidelines

6.1 Quality Guidelines

S. No.	Quality Guidelines	Remarks	Compliant Status
1	Association to Government is demonstrated using Emblem/Logo in proper ratio and colour, prominently displayed on the homepage/homescreen of the website/app.	The government association is demonstrated through the Emblem/Logo	COMPLIANT
2	Ownership information is displayed on the homepage/homescreen and on all important entry pages/screens of the website/app and each subsequent page/screen is a standalone entity in terms of ownership, navigation and context of content.	Ownership information is displayed on the homepage	COMPLIANT
3	Source of all documents, not owned by the dept. that have been reproduced in part or full, is mentioned.	NEED EVIDENCE	NON-COMPLIANT
4	Due permissions have been obtained for publishing any content protected by copyright.	NEED EVIDENCE	NON-COMPLIANT
5	Homepage/homescreen of website displays the last updated/reviewed date.	The last updated/reviewed date is displayed on the homepage of the website.	COMPLIANT
6	Complete information including title, size, format and usage instructions is provided for all downloadable material.	File size and format/type information are not mentioned for the downloadable materials.	NON-COMPLIANT
7	Statement: With respect to each, Circular, Notification, Document, Form, Scheme, Service and Recruitment notice, the following should be clearly listed on the Website: a) Complete title b) Language (if other than English) c) Purpose/procedure to apply (as applicable) d) Validity (if applicable)	Complete details including title, language, purpose/procedure to apply, and validity are clearly provided for the relevant documents, forms, schemes, services, and recruitment notices.	COMPLIANT
8	All outdated Announcements, Tenders, Recruitment notices, News and Press Releases are removed from the website and/or placed into the archives as per the archival policy.	An archival policy is not provided for all the necessary documents.	NON-COMPLIANT
9	All information about the government organization, useful for the citizen and other stakeholders, is present in the 'About Us' section and a mechanism is in place to keep the information up to date.	All relevant information about the government organization is available in the 'About Us' section and is kept up to date.	COMPLIANT

10	Website has a 'Contact Us' page providing complete contact details of important functionaries in the government organization and this is linked from the homepage/homescreen and all relevant places on the website/app.	The 'Contact Us' page is improperly implemented and does not provide complete contact details as required.	NON-COMPLIANT
11	Feedback is collected through online forms and a mechanism is in place to ensure timely response to feedback/queries received through the website.	The feedback page is missing, and no online mechanism is available for collecting and responding to feedback or queries.	NON-COMPLIANT
12	Website provides a prominent link to the 'National Portal' from the homepage and subsequent pages belonging to the National Portal load in the new browser window.	A prominent link to the 'National Portal' is provided on the homepage	COMPLIANT
13	The website has been tested on multiple browsers. Hindi/Regional language fonts have been tested on popular browsers for any inconsistency (loss of layout).	The website has been tested across multiple browsers, including Hindi/Regional language fonts, with no inconsistencies or loss of layout observed.	COMPLIANT
14	The website has a readily available Help section linked from all pages of the website.	The Help section is available but does not provide sufficient or informative guidance to users.	NON-COMPLIANT
15	Website uses Cascading Style Sheets (CSS) to control layouts/styles and incorporates responsive design features to ensure that the interface displays well on different screen sizes.	The chatbot overlaps the content at different screen sizes, affecting the responsive display of the interface.	NON-COMPLIANT
16	Website is readable even when style sheets are switched off or not loaded.	Content overlaps when the CSS is disabled, affecting the readability of the website.	NON-COMPLIANT
17	Proper page title and language attribute along with metadata for page like keywords and description are appropriately included.	Metadata such as keywords and description is not provided for the pages.	NON-COMPLIANT
18	Minimum content as prescribed in the guidelines is present on the homepage/homescreen and all subsequent pages/screens. (a) Government Organization name (alternatively, the name of the project, service etc. as applicable); (b) State emblem of India/Logo (as applicable); (c) About the government Organization (including its main activities and functions); (d) Link to all the major modules/sections of the site; (e) Link to all the citizen services offered by the government Organization; (f) Link to the 'Contact us' page of the website/app; (g) Link to the "Feedback" page; (h) Link to national portal; (i) Search/Site Map; and	The prescribed minimum content, including the organization name, logo, About Us, major modules, citizen services, Contact Us, Feedback, National Portal, Search/Site Map, and Terms and Conditions, is available on the website.	COMPLIANT

	(j) Terms and conditions of use.		
19	Data tables have been provided with necessary tags/markup.	The required <th> tag is missing from the data table, resulting in improper table markup.	NON-COMPLIANT
20	Content of the web page prints correctly on an A4 size paper.	Only part of the content and images are visible when the web page is printed on A4 size paper.	NON-COMPLIANT
21	Website is in the nic.in or gov.in domain. Educational Institutions and Research and Academic Institutions, which are eligible for registration under 'gov.in' may use 'edu.in', 'res.in' or 'ac.in' domains.	The website is hosted under an eligible gov.in or nic.in domain as prescribed by the guidelines.	COMPLIANT
22	API integration with key government platforms (India Portal, DigiLocker, Aadhaar, Single-Sign-On, MyGov, Data Platform, MyScheme) and similar websites of the government 10rganization must be enabled for seamless exchange of Information and data.	API integration with the specified key government platforms is not applicable to the website.	NA
23	The government 10rganization must ensure a consistent user experience and visual identities across all its websites/apps.	The website maintains a consistent user experience and visual identity across its interface.	COMPLIANT
24	Websites/apps must provide integration with popular social media.	The website provides integration with popular social media platforms.	COMPLIANT
25	The language is free from spelling and grammatical errors.	The website content is free from spelling and grammatical errors.	COMPLIANT

6.2 Lifecycle Management Guidelines

S. No.	Lifecycle Management Guidelines	Remarks	Compliant Status
1	The government organisation has nominated a WIM as defined in the guidelines.	The Web Information Manager (WIM) has not been nominated or identified on the website.	NON-COMPLIANT
2	It has been ensured that all stationery of the government organisation as well as advertisements/public messages issued by the government organisation concerned prominently display the URL of the web site.	The website URL is not prominently displayed on the stationery, advertisements, or public messages issued by the government organization.	NON-COMPLIANT

3	Website has the following clearly defined policies and plans approved by the WIM. a) Copyright Policy b) Content Contribution, Moderation and Approval (CMAP) policy c) Content Archival (CAP) policy d) Content Review (CRP) policy e) Hyper linking Policy f) Privacy Policy g) Terms & Conditions h) Website Monitoring Plan. i) Contingency Management Plan j) Security Policy	The required policies and plans approved by the WIM are not available on the website.	NON-COMPLIANT
4	The mechanism is in place to check the accuracy of Hyperlinked Content and clear indications are given when a link leads out to a non-government website.	No message or indication is provided when users are redirected to an external website.	NON-COMPLIANT
5	It is ensured through content moderation and approval policy that Website content is free from offensive/discriminatory language.	Website content is free from offensive or discriminatory language through appropriate content moderation and approval measures.	COMPLIANT
6	Documents/Pages in multiple languages are updated simultaneously.	Documents/pages in multiple languages are not updated consistently, with some pages containing both English and Hindi content.	NON-COMPLIANT
7	Mechanism is in place to ensure that there are no 'broken links' (internal as well as external) or 'Page not found' errors.	A mechanism is in place to ensure that the website is free from broken internal and external links and 'Page not found' errors.	COMPLIANT
8	There are no links to 'under construction' pages.	The website does not contain any links leading to 'under construction' pages.	COMPLIANT
9	Documents are provided either in HTML or other accessible formats.	Documents are provided in HTML or other accessible formats.	COMPLIANT
10	Website is bilingual with a prominent language selection link and uses Unicode characters.	The website is bilingual, provides a prominent language selection link, and uses Unicode characters.	COMPLIANT

6.3 Accessibility Guidelines

S. No.	Accessibility Guidelines	Remarks	Compliant Status
1	All non-text content that is presented to the user has a text alternative that serves the equivalent purpose, except for the situations listed below.	The required alternative text (alt text) is missing for non-text content, preventing equivalent information from being conveyed to users.	NON-COMPLIANT

2	For pre-recorded audio-only and pre-recorded video-only media, the following are true, except when the audio or video is a media alternative for text and is clearly labelled as such: a) Pre-recorded Audio-only: An alternative for time-based media is provided that presents equivalent information for pre-recorded audio-only content. b) Pre-recorded Video-only: Either an alternative for time-based media or an audio track is provided that presents equivalent information for pre-recorded video-only content.	Captions are not provided for the pre-recorded audio and video content, resulting in non-compliance with the accessibility requirement.	NON-COMPLIANT
3	Captions are provided for all pre-recorded audio content in synchronised media, except when the media is a media alternative for text and is clearly labelled as such.	Captions are not provided for all pre-recorded video content, resulting in non-compliance with the accessibility requirement.	NON-COMPLIANT
4	An alternative for time-based media or audio description of the pre-recorded video content is provided for synchronised media, except when the media is a media alternative for text and is clearly labelled as such.	An alternative for the time-based media or audio description is not provided for the pre-recorded video content.	NON-COMPLIANT
5	Captions are provided for all live audio content in synchronised media.	Captions for live audio content in synchronised media are not applicable to the website.	NA
6	Audio description is provided for all pre-recorded video content in synchronised media.	Audio descriptions are provided for all pre-recorded video content in synchronised media.	COMPLIANT
7	Information, structure and relationships conveyed through presentation can be programmatically determined or are available in text.	The H1 heading is missing, and the heading sequence is not properly structured, affecting the programmatic determination of information, structure, and relationships.	NON-COMPLIANT
8	When the sequence in which content is presented affects its meaning, a correct reading sequence can be programmatically determined.	The correct reading sequence of the content can be programmatically determined, ensuring that the meaning is preserved.	COMPLIANT
9	Instructions provided for understanding and operating content do not rely solely on sensory characteristics of components such as shape, colour, size, visual location, orientation, or sound.	Instructions for understanding and operating the content do not rely solely on sensory characteristics such as shape, colour, size, visual location, orientation, or sound.	COMPLIANT
10	Content does not restrict its view and operation to a single display orientation, such as portrait or landscape, unless a specific display orientation is essential.	The chatbot overlaps with the content, affecting the proper view and operation of the website across display orientations.	NON-COMPLIANT

11	The purpose of each input field collecting information about the user can be programmatically determined when: a) The input field serves a purpose identified in the Input Purposes for User Interface Components section; and b) The content is implemented using technologies with support for identifying the expected meaning for form input data.	The purpose of each input field is programmatically determinable, and the expected meaning of the form input data can be identified.	COMPLIANT
12	Colour is not used as the only visual means of conveying information, indicating an action, prompting a response, or distinguishing a visual element.	Colour is not used as the sole visual means of conveying information, indicating actions, prompting responses, or distinguishing visual elements.	COMPLIANT
13	If any audio on a Web page plays automatically for more than 3 seconds, either a mechanism is available to pause or stop the audio, or a mechanism is available to control audio volume independently from the overall system volume level.	Audio that plays automatically for more than 3 seconds provides mechanisms to pause or stop the audio or control its volume independently of the system volume.	COMPLIANT
14	The visual presentation of text and images of text has a contrast ratio of at least 4.5:1, except for the following: a) Large Text: (18 pt. or 14 pt. bold) Large-scale text and images of large-scale text have a contrast ratio of at least 3:1. b) Incidental: Text or images of text that are part of an inactive user interface component, that are pure decoration, that are not visible to anyone, or that are part of a picture that contains significant other visual content, have no contrast requirement. c) Logotypes: Text that is part of a logo or brand name has no contrast requirement.	The text and images of text have contrast issues and do not meet the required minimum contrast ratio.	NON-COMPLIANT
15	Except for captions and images of text, text can be resized without assistive technology up to 200 percent without loss of content or functionality.	At 200% text resizing, the icons overlap with the content, resulting in loss of proper presentation and functionality.	NON-COMPLIANT
16	If the technologies being used can achieve the visual presentation, text is used to convey information rather than images of text except for the following: a) Customizable: The image of text can be visually customised to the user's requirements. b) Essential: A particular presentation of text is essential to the information being conveyed.	The text presented on the banner does not meet the required contrast ratio, affecting the accessibility of the text presentation.	NON-COMPLIANT

17	a) Content can be presented without loss of information or functionality, and without requiring scrolling in two dimensions for: b) Vertical scrolling content at a width equivalent to 320 CSS pixels; c) Horizontal scrolling content at a height equivalent to 256 CSS pixels; d) Except for parts of the content which require a two-dimensional layout for usage or meaning.	At 400% zoom, the content cannot be scrolled properly, resulting in loss of accessibility and functionality.	NON-COMPLIANT
18	The visual presentation of the following has a contrast ratio of at least 3:1 against adjacent colour(s): a) User Interface Components: Visual information required to identify user interface components and states, except for inactive components or where the appearance of the component is determined by the user agent and not modified by the author. b) Graphical Objects: Parts of graphics required to understand the content, except when a particular presentation of graphics is essential to the information being conveyed.	The contrast ratio of the icons does not meet the required minimum of 3:1 against adjacent colours.	NON-COMPLIANT
19	In content implemented using markup languages that support the following text style properties, no loss of content or functionality occurs by setting all of the following and by changing no other style property: a) Line height (line spacing) to at least 1.5 times the font size. b) Spacing following paragraphs to at least 2 times the font size. c) Letter spacing (tracking) to at least 0.12 times the font size. d) Word spacing to at least 0.16 times the font size. e) Exception: Human languages and scripts that do not make use of one or more of these text style properties in written text can conform using only the properties that exist for that combination of language and script.	The website content remains accessible without loss of content or functionality when the specified text spacing properties are applied.	COMPLIANT

20	Where receiving and then removing pointer hover or keyboard focus triggers additional content to become visible and then hidden, the following are true: a) Dismissible: A mechanism is available to dismiss the additional content without moving pointer hover or keyboard focus unless the additional content communicates an input error or does not obscure or replace other content. b) Hover-able: If pointer hover can trigger the additional content, then the pointer can be moved over the additional content without the additional content disappearing. c) Persistent: The additional content remains visible until the hover or focus trigger is removed, the user dismisses it, or its information is no longer valid.	Additional content triggered by pointer hover or keyboard focus can be dismissed, accessed, and remains visible as required without loss of functionality.	COMPLIANT
21	All functionality of the content is operable through a keyboard interface without requiring specific timings for individual keystrokes, except where the underlying function requires input that depends on the path of the user's movement and not just the endpoints.	Most of the icons are not accessible through the keyboard interface, as the Tab key does not move focus to them.	NON-COMPLIANT
22	If keyboard focus can be moved to a component of the page using a keyboard interface, then focus can be moved away from that component using only a keyboard interface and, if it requires more than unmodified arrow or tab keys or other standard exit methods, the user is advised of the method for moving focus away.	The keyboard focus sequence is improper, affecting the expected movement of focus through the page.	NON-COMPLIANT
23	If a keyboard shortcut is implemented in content using only letter (including upper- and lower-case letters), punctuation, number, or symbol characters, then at least one of the following is true: a) Turn off: A mechanism is available to turn the shortcut off. b) Remap: A mechanism is available to remap the shortcut to include one or more non-printable keyboard keys (e.g., Ctrl, Alt). c) Active only on focus: The keyboard shortcut for a user interface component is only active when that component has focus.	Keyboard shortcuts using only character keys comply with the requirement, as the applicable shortcut controls are available through the keyboard without causing unintended activation.	COMPLIANT

24	For each time limit that is set by the content, at least one of the following is true: a) Turn off: The user is allowed to turn off the time limit before encountering it; or Adjust: The user is allowed to adjust the time limit before encountering it over a wide range that is at least ten times the length of the default setting; or b) Extend: The user is warned before time expires and given at least 20 seconds to extend the time limit with a simple action (for example, “press the spacebar”) and the user is allowed to extend the time limit at least ten times; or c) Real-time Exception: The time limit is a required part of a real-time event (for example, an auction) and no alternative to the time limit is possible; or d) Essential Exception: The time limit is essential and extending it would invalidate the activity; or e) 20 Hour Exception: The time limit is longer than 20 hours.	The requirement related to time limits is not applicable to the website.	NA
25	For moving, blinking, scrolling, or auto-updating information, all of the following are true: a) Moving, blinking, scrolling: For any moving, blinking or scrolling information that (1) starts automatically, (2) lasts more than five seconds and (3) is presented in parallel with other content, there is a mechanism for the user to pause, stop, or hide it unless the movement, blinking, or scrolling is part of an activity where it is essential; and b) Auto-updating: For any auto-updating information that (1) starts automatically and (2) is presented in parallel with other content, there is a mechanism for the user to pause, stop, or hide it or to control the frequency of the update unless the auto-updating is part of an activity where it is essential.	Doesn't have stop mechanisms for moving content	NON-COMPLIANT
26	Web pages do not contain anything that flashes more than three times in any one second period, or the flash is below the general flash and red flash thresholds.	The web pages do not contain content that flashes more than three times within any one-second period or exceeds the applicable flash thresholds.	COMPLIANT
27	A mechanism is available to bypass blocks of content that are repeated on multiple Web pages.	A mechanism is available to bypass repeated blocks of content across multiple web pages.	COMPLIANT
28	Web pages have titles that describe the topic or purpose.	The web pages have descriptive titles that clearly indicate their topic or purpose.	COMPLIANT

29	If a Web page can be navigated sequentially and the navigation sequences affect meaning or operation, focusable components receive focus in an order that preserves meaning and operability.	Focusable components receive focus in a logical sequence that preserves the meaning and operability of the web page.	COMPLIANT
30	The purpose of each link can be determined from the link text alone or from the link text together with its programmatically determined link context, except where the purpose of the link would be ambiguous to users in general.	The screen reader does not read the links properly, making the purpose of the links difficult to determine.	NON-COMPLIANT
31	More than one way is available to locate a Web page within a set of Web pages except where the Web Page is the result of, or a step in, a process.	More than one method is available to locate web pages within the set of web pages.	COMPLIANT
32	Headings and labels describe topic or purpose.	Headings and labels clearly describe the topic or purpose of the associated content and controls.	COMPLIANT
33	Any keyboard operable user interface has a mode of operation where the keyboard focus indicator is visible.	The keyboard focus indicator is visible for keyboard-operable user interface components.	COMPLIANT
34	All functionality that uses multipoint or path-based gestures for operation can be operated with a single pointer without a path-based gesture, unless a multipoint or path-based gesture is essential.	All functionality requiring multipoint or path-based gestures can also be operated using a single pointer without requiring such gestures.	COMPLIANT
35	For functionality that can be operated using a single pointer, at least one of the following is true: a) No Down-Event: The down-event of the pointer is not used to execute any part of the function. b) Abort or Undo: Completion of the function is on the up-event and a mechanism is available to abort the function before completion or to undo the function after completion. c) Up Reversal: The up-event reverses any outcome of the preceding down-event. d) Essential: Completing the function on the down-event is essential.	Functionality operated using a single pointer can be completed without unintended activation from the down-event, in accordance with the specified requirements.	COMPLIANT
36	For user interface components with labels that include text or images of text, the name contains the text that is presented visually.	The accessible name of user interface components contains the text presented visually in their labels.	COMPLIANT

37	Functionality that can be operated by device motion or user motion can also be operated by user interface components and responding to the motion can be disabled to prevent accidental actuation, except when: a) Supported Interface: The motion is used to operate functionality through an accessibility supported interface. b) Essential: The motion is essential for the function and doing so would invalidate the activity. c) Functionality that can be operated by device motion or user motion must also be operable by user interface components and responding to the motion can be disabled to prevent accidental actuation, except when: d) Supported Interface: The motion is used to operate functionality through an accessibility supported interface. e) Essential: The motion is essential for the function and doing so would invalidate the activity.	Functionality operated through device or user motion is not applicable to the website.	NA
38	The default human language of each Web page can be programmatically determined.	The default human language of each web page can be programmatically determined.	COMPLIANT
39	The human language of each passage or phrase in the content can be programmatically determined except for proper names, technical terms, words of indeterminate language and words or phrases that have become part of the vernacular of the immediately surrounding text.	The human language of each passage or phrase in the content can be programmatically determined, where applicable.	COMPLIANT
40	When any user interface component receives focus, it does not initiate a change of context.	User interface components do not initiate a change of context when they receive focus.	COMPLIANT
41	Changing the setting of any user interface component does not automatically cause a change of context unless the user has been advised of the behaviour before using the component.	Changing the settings of user interface components does not automatically cause a change of context without prior notification to the user.	COMPLIANT
42	Navigational mechanisms that are repeated on multiple Web pages within a set of Web pages occur in the same relative order each time they are repeated, unless a change is initiated by the user.	Repeated navigational mechanisms appear in the same relative order across the web pages.	COMPLIANT
43	Components that have the same functionality within a set of Web pages are identified consistently.	Components with the same functionality are identified consistently across the set of web pages.	COMPLIANT
44	If an input error is automatically detected, the item that is in error is identified and the error is described to the user in text.	Labels are missing for the input fields, preventing input errors from being clearly	NON-COMPLIANT

		identified and described to users.	
45	Labels or instructions are provided when content requires user input.	Appropriate labels or instructions are provided for content that requires user input.	COMPLIANT
46	If an input error is automatically detected and suggestions for correction are known, then the suggestions are provided to the user, unless it would jeopardise the security or purpose of the content.	The requirement for providing suggestions to correct automatically detected input errors is not applicable to the website.	NA
47	For Web pages that cause legal commitments or financial transactions for the user to occur, that modify or delete user-controllable data in data storage systems, or that submit user test responses, at least one of the following is true: a) Reversible: Submissions are reversible. b) Checked: Data entered by the user is checked for input errors and the user is provided an opportunity to correct them. c) Confirmed: A mechanism is available for reviewing, confirming and correcting information before finalising the submission.	The requirement for reviewing, confirming, correcting, or reversing user submissions is not applicable to the website.	NA
48	In content implemented using markup languages, elements have complete start and end tags, elements are nested according to their specifications, elements do not contain duplicate attributes and any IDs are unique, except where the specifications allow these features.	Errors were identified in the HTML and CSS validation, indicating issues in the markup implementation.	NON-COMPLIANT
49	For all user interface components (including but not limited to form elements, links and components generated by scripts), the name and role can be programmatically determined; states, properties and values that can be set by the user can be programmatically set; and notification of changes to these items is available to user agents, including assistive technologies.	The name and role of some user interface components cannot be programmatically determined, and their states, properties, and values are not properly exposed to assistive technologies.	NON-COMPLIANT
50	In content implemented using markup languages, status messages can be programmatically determined through role or properties such that they can be presented to the user by assistive technologies without receiving focus.	Status messages are not properly conveyed to assistive technologies, as they are not being read by the screen reader.	NON-COMPLIANT

7. Summary of Key Findings

Sr. No.	Vulnerability Name	Status
1.	File Size and Format Information Not Provided	OPEN
2.	Archival Policy Not Provided for Required Documents	OPEN
3.	Contact Us Page Does Not Provide Complete Information	OPEN
4.	Feedback Page Not Available	OPEN
5.	Help Section Does Not Provide Sufficient Information	OPEN
6.	Chatbot Overlaps Content at Different Screen Sizes	OPEN
7.	Content Overlaps When CSS Is Disabled	OPEN
8.	Page Metadata Not Provided	OPEN
9.	Inconsistent Language Content on Web Pages	OPEN
10.	No Notification Provided for External Website Redirection	OPEN
11.	Content and Images Partially Visible During Printing	OPEN
12.	Web Information Manager (WIM) Not Identified	OPEN
13.	Website URL Not Displayed on Documents	OPEN
14.	WIM-Approved Policies and Plans Not Available	OPEN
15.	Alternative Text Missing for Non-Text Content	OPEN
16.	Captions Not Provided for Pre-Recorded Videos	OPEN
17.	H1 Heading Missing and Heading Sequence Improper	OPEN
18.	Insufficient Colour Contrast	OPEN
19.	Icons Overlap at 200% Text Resize	OPEN
20.	Table Header (<th>) Tag Missing	OPEN
21.	Content Cannot Be Properly Scrolled at 400% Zoom	OPEN
22.	Most Icons Are Not Keyboard Accessible	OPEN
23.	Icons Do Not Meet Required Contrast Ratio	OPEN
24.	Keyboard Focus Disappears at End of Page	OPEN
25.	No Mechanism to Stop or Pause Moving Content	OPEN
26.	Link Information Is Not Properly Conveyed by Screen Reader	OPEN
27.	Labels Missing for Input Fields	OPEN
28.	Status Messages Are Not Properly Conveyed by Screen	OPEN

	Reader	
29.	Some Content Is Not Properly Conveyed by Screen Reader	OPEN
30.	Error Identified in HTML and CSS Validation	OPEN

→ OPEN




→ CLOSED




CONFIDENTIAL


8. Detailed Technical Report with Recommendations


8.1 File Size and Format Information Not Provided

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	
The website provides downloadable materials without mentioning the corresponding file size and file format/type information. Users are therefore not provided with sufficient details about the files before downloading them. The absence of this information makes it difficult for users to understand the type and size of the downloadable content in advance. This information is particularly relevant for users who need to determine compatibility or estimate the download requirements. The downloadable materials should provide the required file details in accordance with the applicable GIGW requirements.	
IMPACT	
The absence of file size and format/type information may make it difficult for users to identify the nature and download requirements of available materials. Users may not be able to determine whether a particular file format is suitable for their device or software before initiating the download. This can reduce the clarity and usability of downloadable resources provided through the website. Providing the relevant file details helps users make informed decisions before accessing or downloading the material.	
AFFECTED URL	
https://www.dosje.gov.in/annual-reports/ https://www.dosje.gov.in/acts-rules/	
Throughout the website	
RECOMMENDATIONS	
The website should clearly mention the file size and format/type for each downloadable material. The information should be presented in a clear and consistent manner alongside the corresponding download link so that users can identify the file details before downloading it.	
PROOF OF CONCEPT	
	



8.2 Archival Policy Not Provided for Required Documents


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	An archival policy is not provided for all the necessary documents available on the website. The website does not clearly specify the process for archiving outdated or superseded documents. The absence of an archival policy makes it unclear how such documents are managed over time. Necessary documents should be covered under a defined archival process in accordance with the applicable GIGW requirements. The archival policy should clearly define how relevant documents are retained, archived, or removed.
IMPACT	The absence of an archival policy may result in inconsistent management of documents available on the website. Users may have difficulty identifying whether older documents are current, archived, or no longer applicable. This can affect the clarity and organization of information presented on the website. A defined archival process helps maintain relevant and properly managed online content. It also provides a consistent approach for handling outdated documents.
AFFECTED URL	https://www.dosje.gov.in/circulars-notifications/ https://www.dosje.gov.in/annual-reports/ Throughout the website
RECOMMENDATIONS	The website should establish and provide an appropriate archival policy covering all necessary documents. The policy should define the process for identifying, retaining, archiving, and removing outdated documents. Relevant documents should be managed consistently according to the defined archival procedure. The archival information should be clearly documented and maintained to ensure proper content management.
PROOF OF CONCEPT	 The screenshot shows the 'Documents' section of the DOSJNE website. A table lists various documents, including 'DOPT OM's & Order(English)', 'Reservation for candidates from Other Backward Classes', 'DOPT OM's & Orders', 'Cancellation notice regarding the advertisement for engagement of PMU State Coordinators under the PMU', and 'Statement 10A 2025-2026'. The 'Cancellation notice' document is highlighted with a red box, showing its date as 20/04/2026.



The screenshot shows the website of the Government of India, Ministry of Social Justice & Empowerment, Department of Social Justice & Empowerment. The page displays a list of annual reports under the 'Documents' tab. A red box highlights the 'Documents' column for the 2023-24 and 2024-25 reports.

Report Title	Associated Organisation	Year	Size	Document 1	Document 2	Download
Annual Report 2023-24	NISD	2023	49.18 MB	01/01/2023	NA	Download
Annual Report 2024-25	BJRNF	2024	7.04 MB	01/05/2024	02/12/2025	Download
Annual Report 2023-24	BJRNF	2023	7.65 MB	01/05/2023	01/05/2024	Download
36th Annual Report 2024-25	NSFDC	2024	43.58 MB	20/11/2024	20/11/2025	Download
Annual Report 2025-26 (English)	MoSJE	NA	6.64 MB	NA	NA	Download
Annual Report 2025-26 (Hindi)	MoSJE	2026	89.20 MB	15/04/2026	30/04/2028	Download


8.3 Contact Us Page Does Not Provide Complete Information

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The "Contact Us" page does not provide complete and appropriate contact information as required. The available information is insufficient for users to obtain the necessary details for contacting the organization. Required contact details are not properly presented on the page. This may make it difficult for users to identify the appropriate contact channel. The Contact Us page should provide complete and relevant information as prescribed by the applicable GIGW requirements.
IMPACT	The absence of complete contact information may make it difficult for users to communicate with the concerned government organization. Users may not be able to identify the appropriate contact details or channel for their queries. This can affect the accessibility and usability of the contact facility provided through the website. Clear and complete contact information helps users communicate with the organization effectively. Providing the required details improves the overall usefulness of the Contact Us page.
AFFECTED URL	https://www.dosje.gov.in/contact-us/?org=mosje
RECOMMENDATIONS	The "Contact Us" page should be updated to provide complete and accurate contact information. All applicable contact details should be clearly presented and organized for easy access. The information should enable users to identify the appropriate channel for contacting the organization. The page should be reviewed regularly to ensure that the provided contact information remains accurate and up to date.
PROOF OF CONCEPT	


8.4 Feedback Page Not Available


STATUS	OPEN
REFERENCE	<u>GIGW GUIDELINES 3.0</u>
DESCRIPTION	
The website does not provide a dedicated Feedback page for users. No appropriate online mechanism is available for users to submit their feedback or queries through the website. The absence of a feedback facility limits the available means for users to communicate their comments or suggestions. A suitable mechanism should be provided to enable users to submit feedback conveniently. The feedback facility should be implemented in accordance with the applicable GIGW requirements.	
IMPACT	
The absence of a Feedback page may prevent users from conveniently providing their comments, suggestions, or queries. Users may not have a clearly defined channel through which they can communicate their feedback to the organization. This can reduce the effectiveness of user interaction with the website. A dedicated feedback mechanism provides users with an appropriate channel for submitting their inputs. It also supports better communication between website users and the concerned organization.	
AFFECTED URL	
https://www.dosje.gov.in/	
RECOMMENDATIONS	
A dedicated Feedback page should be provided on the website. The page should include an appropriate online mechanism for users to submit their feedback, comments, or queries. The submitted feedback should be handled through a defined process for review and response. The feedback facility should be clearly accessible from the relevant sections of the website.	

8.5 Help Section Does Not Provide Sufficient Information


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The Help section available on the website does not provide sufficient and informative guidance to users. The information provided in the section is inadequate to assist users in understanding or using the website effectively. Important guidance and relevant instructions are not sufficiently covered. The Help section should provide clear and useful information addressing common user requirements. The content should be presented in a simple and understandable manner.
IMPACT	The lack of informative content in the Help section may make it difficult for users to understand how to use various website features and services. Users may not receive sufficient guidance when they require assistance while navigating the website. This can affect the overall usability of the website. Providing clear and relevant help information can assist users in accessing available services and information more effectively.
AFFECTED URL	https://www.dosje.gov.in/home-page/help/
RECOMMENDATIONS	The Help section should be enhanced with clear, relevant, and informative guidance for users. Appropriate instructions should be provided for commonly used website features, services, and functions. The information should be organized in a clear and easy-to-understand manner. The Help section should also be reviewed periodically to ensure that the provided guidance remains relevant and useful.
PROOF OF CONCEPT	

8.6 Chatbot Overlaps Content at Different Screen Sizes


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The chatbot overlaps with the website content when viewed at different screen sizes. The chatbot position does not adapt appropriately to changes in the available screen space. As a result, portions of the underlying content may be covered by the chatbot interface. This affects the proper presentation of the website across different screen dimensions. The chatbot should be positioned in a manner that does not obstruct the website content.
IMPACT	The overlap of the chatbot with website content may affect the visibility and accessibility of the underlying information. Users may have difficulty viewing or interacting with content that is covered by the chatbot. This issue can become more noticeable when the website is accessed on screens with different dimensions. It may also affect the overall usability and responsive presentation of the website. Ensuring proper positioning can help maintain clear access to the website content.
AFFECTED URL	https://www.dosje.gov.in/ https://www.dosje.gov.in/about-us/ Throughout the website
RECOMMENDATIONS	The chatbot should be implemented with responsive positioning that adapts appropriately to different screen sizes. It should not overlap or obscure important website content or interactive elements. The chatbot placement should be tested across different viewport dimensions and devices. Appropriate spacing and positioning should be maintained to ensure that all underlying content remains visible and accessible.
PROOF OF CONCEPT	




8.7 Content Overlaps When CSS Is Disabled


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The website content overlaps when CSS is disabled during testing. The content does not maintain a proper structure and layout in the absence of CSS styling. As a result, different elements may appear over one another and affect the presentation of the information. This makes the content difficult to read and understand in its unstyled state. The website should maintain a logical and readable content structure when CSS is disabled.
IMPACT	Content overlapping when CSS is disabled may affect the readability and presentation of information on the website. Users may experience difficulty in identifying and understanding individual content elements. The improper arrangement can also affect the logical flow of the page content. This may reduce the usability of the website when styles are unavailable or not applied. Maintaining a proper content structure helps ensure that information remains understandable.
AFFECTED URL	https://www.dosje.gov.in/
RECOMMENDATIONS	The website should be implemented so that content remains logically structured and readable when CSS is disabled. HTML elements should follow an appropriate document structure without relying entirely on CSS positioning. Overlapping elements should be corrected to ensure that content remains distinguishable and accessible. The pages should be tested with CSS disabled to verify proper content presentation and reading order.
PROOF OF CONCEPT	 The screenshot shows the website dosje.gov.in with CSS disabled. The language selection menu is highlighted with a red box, showing a list of languages including English, Gujarati, Hindi, Kannada, Malayalam, Marathi, Nepali, Odia, Punjabi, Sanskrit, Santali, Sindhi, and Tamil. The text is overlapping and difficult to read, demonstrating the issue described in the report.

8.8 Page Metadata Not Provided


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The required metadata for the web pages is not provided. Metadata such as page keywords and description is missing from the relevant pages. This information helps describe the purpose and content of individual web pages. The absence of these metadata elements results in incomplete page information. The required metadata should be appropriately defined for the applicable pages.
IMPACT	The absence of page metadata may affect the proper description and identification of the website content. Users and systems may not receive sufficient information about the purpose and content of individual pages. Missing keywords and descriptions can also result in incomplete metadata implementation. Providing appropriate metadata helps maintain consistent and descriptive information for web pages. This supports better content identification and management.
AFFECTED URL	https://www.dosje.gov.in/
RECOMMENDATIONS	The website should provide appropriate metadata for all relevant web pages. Page descriptions and relevant keywords should be defined according to the content and purpose of each page. The metadata should be implemented consistently across the website. The pages should be reviewed to ensure that the required metadata elements are present and appropriately maintained
PROOF OF CONCEPT	 The screenshot shows the website dosje.gov.in in a browser. The DevTools console is open, displaying the HTML source code. The search bar in DevTools is set to 'meta description', but no results are shown, indicating that no meta tags are present in the page's HTML. The website content visible includes the header of the Department of Social Justice & Empowerment, a section for 'SAMAVESH' (Single Access Mechanism for all), and an 'About Us' section.




8.9 Inconsistent Language Content on Web Pages


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The content on the website is not consistently presented in a single selected language. Portions of the same page are displayed in Hindi, while other portions are displayed in English. This results in inconsistent language presentation within the website content. The language content should be properly synchronized and presented consistently across the applicable pages. The website should ensure that content provided in multiple languages is appropriately maintained and updated.
IMPACT	Inconsistent language presentation may make it difficult for users to understand the complete information provided on a web page. Users may encounter sections in a language different from the one selected for viewing the website. This can affect the clarity and consistency of the information presented. It may also result in an inconsistent user experience when navigating between language versions. Maintaining consistent language content helps users access the intended information more effectively.
AFFECTED URL	https://www.dosje.gov.in/organisation/national-commission-for-safai-karamcharis/
RECOMMENDATIONS	The website should ensure that content is presented consistently according to the language selected by the user. Hindi and English versions of the content should be properly separated and maintained as applicable. Corresponding language versions should contain complete and consistent information. The website should also ensure that updates to content are reflected appropriately across the available language versions.
PROOF OF CONCEPT	 The screenshot shows the official website of the Government of India, Department of Social Justice & Empowerment. The page features a navigation menu with options like 'Home', 'Department', 'Associated Organisations', 'Offerings', 'Documents', 'Events & Gallery', and 'Connect'. The main content area displays three news items, each with a photograph and a headline in Hindi, followed by a brief description in English. This mix of languages within the same section demonstrates the inconsistency in language presentation.

8.10 No Notification Provided for External Website Redirection

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	No notification or message is provided when users are redirected from the website to an external website. The website does not clearly indicate that the selected link will take users outside the current website. This may make it difficult for users to identify external links before accessing them. An appropriate indication should be provided for links that redirect users to external websites. The notification should be clear and easily understandable to users.
IMPACT	The absence of an external redirection message may make it difficult for users to identify when they are leaving the current website. Users may access an external website without receiving prior information about the redirection. This can affect the clarity and transparency of the navigation experience. Providing a clear indication helps users understand the destination of external links before proceeding. It also provides better awareness when navigating to external websites.
AFFECTED URL	https://www.dosje.gov.in/
RECOMMENDATIONS	The website should provide a clear notification or indication before redirecting users to an external website. External links should be appropriately identified so that users can distinguish them from internal website links. The notification should be presented in a clear and understandable manner. All relevant external links should be reviewed to ensure that appropriate redirection information is provided.
PROOF OF CONCEPT	 The screenshot shows the DOSJNE website (dosje.gov.in/tenders/) with a search bar and navigation menu. A red box highlights the 'Apply online for PMU' link in the 'Offerings' dropdown menu. The link is an external URL, but no notification is provided when it is clicked, leading to an external website.

8.11 Content and Images Partially Visible During Printing


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	Only part of the website content and images are visible when the web page is printed. Some content and images are not completely rendered in the printed output. This results in partial visibility of the information available on the web page. The page content should be properly formatted to ensure that all relevant information is visible when printed. The printing layout should be implemented in accordance with the applicable GIGW requirements.
IMPACT	Partial visibility of content and images during printing may prevent users from accessing the complete information in the printed version. Important portions of the webpage may be missing or truncated in the print output. This can affect the readability and completeness of the printed information. Users may not be able to obtain an accurate printed representation of the webpage. Ensuring proper print formatting helps maintain the availability of complete content.
AFFECTED URL	https://www.dosje.gov.in/ https://www.dosje.gov.in/about-us/ Throughout the website
RECOMMENDATIONS	The website should be configured to ensure that all relevant content and images are properly displayed when printed. The print layout should be reviewed and adjusted to prevent content from being cut off or omitted. Print-specific styling should be implemented where required to provide a complete representation of the webpage. The website should be tested using standard print settings and A4 paper size to verify proper rendering.
PROOF OF CONCEPT	




8.12 Web Information Manager (WIM) Not Identified

STATUS	OPEN
REFERENCE	<u>GIGW GUIDELINES 3.0</u>
DESCRIPTION	
The Web Information Manager (WIM) has not been identified on the website. The website does not provide information regarding the nominated WIM responsible for managing the web information. The required WIM details are therefore not available for users to identify the concerned authority. The WIM information should be clearly provided on the website as required by the applicable GIGW guidelines. The details should be kept accurate and up to date.	
IMPACT	
The absence of WIM information may make it difficult for users to identify the authority responsible for managing the website information. Users may not have a clear point of reference for website-related information or concerns. This can affect transparency regarding the management of web content. Providing the relevant WIM details helps establish clear responsibility for website information management. It also supports appropriate communication with the concerned authority.	
AFFECTED URL	
https://www.dosje.gov.in/	
RECOMMENDATIONS	
The website should clearly identify the nominated Web Information Manager (WIM). Relevant details of the WIM should be provided in an easily accessible section of the website. The information should be accurate, complete, and maintained whenever there is a change in the nominated official. The website should be reviewed periodically to ensure that the WIM information remains current.	

8.13 Website URL Not Displayed on Documents

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The website URL is not displayed on the relevant documents issued by the government organization. The documents do not prominently mention the official website address for reference. This makes it difficult for users to identify the associated official website directly from the documents. The website URL should be clearly displayed on applicable documents as required by the GIGW guidelines. The URL should be presented in a prominent and easily identifiable manner.
IMPACT	The absence of the website URL on documents may make it difficult for users to identify the official website associated with the issued document. Users may not have a direct reference to access the corresponding online information or services. This can reduce the visibility of the official website in documents circulated to users. Providing the URL helps users identify and access the relevant website conveniently. It also supports consistent identification of the organization's official web presence.
AFFECTED URL	https://www.dosje.gov.in/vacancies/ https://www.dosje.gov.in/tenders/ Throughout the website
RECOMMENDATIONS	The official website URL should be prominently displayed on applicable documents issued by the organization. The URL should be clearly visible and presented in a consistent location or format. Relevant documents, including stationery and public communications where applicable, should be reviewed to ensure that the website address is included. The displayed URL should be verified to ensure that it points to the official website.
PROOF OF CONCEPT	





CONFIDENTIAL

8.14 WIM-Approved Policies and Plans Not Available


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	
The policies and plans required to be approved by the Web Information Manager (WIM) are not available on the website. The website does not provide the applicable policies and plans for reference by users. This includes the required documentation related to website management and governance. The absence of these policies and plans indicates that the required information has not been made available through the website. The applicable WIM-approved policies and plans should be published as required by the GIGW guidelines.	
IMPACT	
The absence of WIM-approved policies and plans may limit the availability of important website governance information to users. Users may not be able to access the applicable policies governing the management and operation of the website. This can reduce transparency regarding the processes followed for website administration and content management. Providing the required policies and plans helps users understand the applicable website governance requirements. It also ensures that the relevant documentation is readily available for reference.	
AFFECTED URL	
https://www.dosje.gov.in/	
RECOMMENDATIONS	
The website should provide all applicable policies and plans approved by the WIM. The required documents should be published in an easily accessible and clearly identified section of the website. The policies and plans should be kept current and updated whenever revisions are approved. The website should also be reviewed periodically to ensure that all required WIM-approved documentation remains available.	

8.15 Alternative Text Missing for Non-Text Content


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	Alternative text is missing for some non-text content available on the website. The affected images and other non-text elements do not provide an appropriate text alternative. This prevents the equivalent information or purpose of the non-text content from being conveyed through text. Users relying on assistive technologies may therefore not receive the intended information. Appropriate alternative text should be provided for relevant non-text content.
IMPACT	Missing alternative text may prevent users of assistive technologies from understanding the information or purpose conveyed by images and other non-text content. Screen reader users may not receive meaningful information for affected elements. This can result in an incomplete understanding of the page content. Providing suitable alternative text helps ensure that equivalent information is available in an accessible form.
AFFECTED URL	https://www.dosje.gov.in/ https://www.dosje.gov.in/organisation/pradhan-mantri-anusuchit-jaati-abhyuday-yojnapm-ajay/ Throughout the website
RECOMMENDATIONS	Appropriate alternative text should be provided for all relevant non-text content. The alternative text should accurately describe the purpose or information conveyed by the image or element. Decorative images should be appropriately marked so they are not unnecessarily announced by assistive technologies. The implementation should be reviewed using accessibility testing tools and screen readers.
PROOF OF CONCEPT	 The screenshot shows the homepage of dosje.gov.in. Several elements are highlighted with red boxes and labeled 'alt=""', indicating missing alternative text: - The Government of India logo at the top left. - The Department of Social Justice & Empowerment logo. - The Digital India logo. - The SAMAVESH banner with the text 'Single Access Mechanism for All Verticals of Empowerment & Social Harmony'. - A large image of a statue in front of a building. - A small circular logo in the bottom right corner.




8.16 Captions Not Provided for Pre-Recorded Videos


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	Captions are not provided for the pre-recorded video content available on the website. The videos do not provide synchronized text alternatives for the spoken audio and relevant audio information. This may prevent users who are deaf or hard of hearing from accessing the auditory information presented in the videos. Captions should be provided for all applicable pre-recorded video content. The captions should accurately represent the relevant audio information.
IMPACT	The absence of captions may prevent users who are deaf or hard of hearing from fully understanding the information presented through pre-recorded videos. Important spoken information or relevant audio content may not be available in an accessible text format. This can result in unequal access to the information conveyed through multimedia content. Providing captions helps ensure that the audio information is available to a wider range of users.
AFFECTED URL	https://www.dosje.gov.in/gallery/?type=videos
RECOMMENDATIONS	Captions should be provided for all applicable pre-recorded video content. The captions should be synchronized with the corresponding audio and accurately convey relevant spoken information. They should remain readable and properly synchronized throughout the video. All existing and newly published pre-recorded videos should be reviewed to ensure appropriate captioning is provided.
PROOF OF CONCEPT	


8.17 H1 Heading Missing and Heading Sequence Improper

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The H1 heading is missing from the affected web pages, and the heading sequence is not properly structured. The headings do not follow a logical hierarchy that clearly represents the structure of the page content. This may make it difficult for users of assistive technologies to understand the organization of the content. Proper heading structure should be maintained throughout the web pages. The heading hierarchy should accurately reflect the relationship between different sections of content.
IMPACT	An improper heading structure may make it difficult for users to navigate and understand the organization of the page content. Screen reader users may have difficulty identifying the main topic and relationships between different sections. The absence of an H1 heading can also affect the clear identification of the primary content of the page. Maintaining a logical heading hierarchy helps users understand and navigate the content more effectively.
AFFECTED URL	https://www.dosje.gov.in/ https://www.dosje.gov.in/gallery/ https://www.dosje.gov.in/gallery/?type=videos Throughout the website
RECOMMENDATIONS	A suitable H1 heading should be provided to identify the main topic or purpose of each applicable page. Heading levels should be arranged in a logical and consistent hierarchy. The sequence should accurately represent the structure and relationships of the page content. The heading structure should also be tested using accessibility tools and screen readers to verify proper programmatic interpretation.
PROOF OF CONCEPT	 The screenshot shows the website of the Government of India, Ministry of Social Justice & Empowerment, Department of Social Justice & Empowerment. The page features a header with the Government of India logo and the department name. Below the header, there is a navigation bar with links to Home, Department, Associated Organisations, Offerings, and Documents. The main content area displays a banner for 'SAMAVESH' (Single Access Mechanism for All Verticals of Empowerment & Social Harmony) with a group photo of officials. On the left side, there is a sidebar with a 'HeadingsMap' section, which lists various headings and sub-headings, including 'About Us', 'Cumulative Disbursement', 'Beneficiary Coverage', 'Release of Funds', 'Our Offerings', 'Students', 'What's New', 'Our Organisations', and 'Recent Documents'. The sidebar also includes a search bar and a 'Explore' button.





8.18 Insufficient Colour Contrast

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	A colour contrast issue was identified on the affected web pages. The contrast between the foreground content and its background does not meet the applicable minimum contrast requirements. This may make the content difficult to distinguish, particularly for users with visual impairments. The affected text and visual content should have sufficient contrast against the background. The contrast should be maintained in accordance with the applicable WCAG requirements.
IMPACT	Insufficient colour contrast may make text and other visual information difficult to perceive and distinguish. Users with low vision or other visual impairments may experience difficulty reading the affected content. This can affect the accessibility and readability of information presented on the website. Adequate contrast helps ensure that content remains clearly perceivable by users.
AFFECTED URL	https://www.dosje.gov.in/ https://www.dosje.gov.in/about-us/ Throughout the website
RECOMMENDATIONS	The colour contrast of the affected content should be adjusted to meet the applicable WCAG minimum contrast requirements. Foreground and background colours should be selected to provide sufficient visual distinction. The contrast should be verified using an appropriate accessibility contrast-checking tool. All affected pages and components should be reviewed to ensure consistent contrast compliance.
PROOF OF CONCEPT	 The screenshot shows the homepage of the Government of India Department of Social Justice & Empowerment. A WCAG Checker overlay is visible on the right side of the page, indicating several contrast failures. The failures listed are: - Normal text AA: FAIL (4.5:1) - Large text AA: FAIL (3:1) - Normal text AAA: FAIL (7:1) - Large text AAA: FAIL (4.5:1) - CUMULATIVE DISBURSEMENT: 1:1 (Normal) - Crore: 1:1 (Normal) - Scholarships for Scheduled Castes: 1:1 (Normal) - BENEFICIARY COVERAGE: 1:1 (Normal) - Crore: 1:1 (Normal) - Cumulative across all schemes: 1:1 (Normal) - RELEASE OF FUNDS, FY 20...: 1:1 (Normal) The website content includes sections for CUMULATIVE DISBURSEMENT (₹67,977 Crore), BENEFICIARY COVERAGE (19.82 Crore), and RELEASE OF FUNDS, FY 2025-26 (₹8,731 Crore).




8.19 Icons Overlap at 200% Text Resize

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The icons overlap with the surrounding content when the text size is increased to 200%. The affected interface elements do not maintain proper spacing and positioning at the increased text size. This results in overlapping visual elements and affects the presentation of the content. The affected icons should remain properly positioned and accessible when text is resized. The website should maintain its functionality and readability at 200% text resizing.
IMPACT	Icon overlap at 200% text resizing may make affected interface elements difficult to identify or operate. Users who require larger text may experience difficulty accessing the affected content or controls. The overlapping elements can also affect the overall readability and usability of the page. Maintaining proper spacing and positioning helps ensure that content remains accessible when text is enlarged.
AFFECTED URL	https://www.dosje.gov.in/ https://www.dosje.gov.in/about-us/ Throughout the website
RECOMMENDATIONS	The affected icons and interface elements should be adjusted to prevent overlap when text is resized to 200%. The page layout should use responsive sizing and spacing that accommodates increased text size. All relevant interactive elements should remain visible and operable without loss of functionality. The website should be tested at 200% text resizing to verify proper presentation and accessibility.
PROOF OF CONCEPT	 The screenshot shows the DOSJNE website at 200% text resize. The browser address bar shows 'dosje.gov.in'. The page header includes the Government of India logo, 'Gov. of India', a 'Login' button, and a 'BETA' label. The main header identifies the 'Department of Social Justice & Empowerment' and features the 'Digital India' logo. A search bar is present with the placeholder text 'Search Schemes, Services, Documents'. The footer contains the text 'Contents of this website owned and managed by Department of Social Empowerment, Ministry of Social Justice and Empowerment, GOI'. A circular logo with a robot character is visible in the bottom right corner. Red boxes highlight the search bar and the circular logo, indicating areas of concern for icon overlap.




8.20 Table Header (<th>) Tag Missing

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The required <th> tag is missing from the affected data table. The table headers are therefore not properly identified using the appropriate HTML markup. This may prevent assistive technologies from correctly determining the relationship between table headers and their corresponding data cells. Proper table markup should be used to define the structure and relationships within the table. The affected tables should be implemented according to the applicable accessibility requirements.
IMPACT	The absence of <th> elements may make it difficult for screen reader users to understand the structure and relationships within the data table. Users may not be able to clearly identify which headings correspond to the associated data cells. This can affect the interpretation and accessibility of tabular information. Properly marked-up table headers help assistive technologies present the table structure more effectively.
AFFECTED URL	https://www.dosje.gov.in/about-us/
RECOMMENDATIONS	The appropriate <th> elements should be added to identify the header cells of the affected data tables. Table headers should be correctly associated with their corresponding data cells using suitable HTML markup. The table structure should be reviewed to ensure that rows, columns, and headers are programmatically determinable. The implementation should also be tested using accessibility tools and screen readers.
PROOF OF CONCEPT	


8.21 Content Cannot Be Properly Scrolled at 400% Zoom

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The website content cannot be properly scrolled when the page is viewed at 400% zoom. The increased zoom level affects the presentation and accessibility of the page content. Users are unable to access all the content through normal scrolling at the increased zoom level. This may result in portions of the content becoming inaccessible or difficult to reach. The website should maintain proper content reflow and scrolling at 400% zoom.
IMPACT	The inability to scroll properly at 400% zoom may prevent users who require increased magnification from accessing the complete page content. Important information or interface elements may become difficult to reach or view. This can affect the usability and accessibility of the website for users with low vision. Proper reflow and scrolling help ensure that content remains accessible at higher zoom levels.
AFFECTED URL	https://www.dosje.gov.in/ https://www.dosje.gov.in/about-us/ Throughout the website
RECOMMENDATIONS	The website should be implemented to support proper content reflow and scrolling at 400% zoom. Horizontal or other scrolling limitations that prevent access to content should be addressed where applicable. All important content and functionality should remain available without loss of information. The affected pages should be tested at 400% zoom to verify proper reflow, scrolling, and accessibility.
PROOF OF CONCEPT	

8.22 Most Icons Are Not Keyboard Accessible

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The Tab key does not move focus to most of the icons available on the website. The affected icons or associated interactive elements are not accessible through keyboard navigation. This prevents keyboard users from reaching and interacting with the affected controls. All interactive icons should be included in the keyboard navigation sequence where applicable. The keyboard focus should be clearly provided for operable interface components.
IMPACT	The inability to access most icons using the Tab key may prevent keyboard-only users from reaching or operating the associated functionality. Users who cannot use a mouse may therefore have difficulty interacting with affected controls. This can limit access to functionality provided through the icons. Ensuring keyboard accessibility allows users to navigate and operate interactive components effectively.
AFFECTED URL	https://www.dosje.gov.in/
RECOMMENDATIONS	All interactive icons should be made accessible through the keyboard interface. The affected elements should be implemented using appropriate interactive controls and included in the logical tab sequence. A visible focus indicator should be provided when the elements receive keyboard focus. The website should be tested using keyboard-only navigation to verify that all interactive icons can be reached and operated.
PROOF OF CONCEPT	


8.23 Icons Do Not Meet the Required Contrast Ratio

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The contrast ratio of the affected icons does not meet the applicable minimum contrast requirement. The icons do not provide sufficient visual distinction against the adjacent background colours. This may make the affected icons difficult to identify or perceive for some users. The contrast of graphical user interface components should meet the applicable accessibility requirements. The affected icons should be adjusted to provide sufficient contrast.
IMPACT	Insufficient icon contrast may make the affected controls difficult to identify or distinguish from the surrounding content. Users with visual impairments or low vision may experience difficulty perceiving the icons. This can affect the accessibility and usability of functionality represented by the affected icons. Adequate contrast helps users clearly identify interface components and their states.
AFFECTED URL	https://www.dosje.gov.in/
RECOMMENDATIONS	The colour combination of the affected icons and their adjacent backgrounds should be adjusted to meet the applicable WCAG contrast requirements. A minimum contrast ratio of 3:1 should be maintained for applicable user interface components and graphical objects. The affected icons should be tested using an appropriate contrast-checking tool. Similar icons across the website should also be reviewed for consistent contrast compliance.
PROOF OF CONCEPT	 The screenshot displays the website dosje.gov.in and a contrast checker tool. The website banner for 'Mann Ki Baat' on 27th September, 2026, is visible. The contrast checker tool shows a background color of #FBF1D6 with a contrast ratio of 1.02:1, which fails WCAG AA and AAA requirements.


8.24 Keyboard Focus Disappears at the End of the Page


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	
The keyboard focus indicator disappears when the Tab key reaches the end of the website content. The focus is not visibly maintained on the last focusable element during keyboard navigation. This makes it difficult for keyboard users to determine the current focus position. The focus indicator should remain visible while navigating through focusable components. The keyboard focus should be managed consistently throughout the page.	
IMPACT	
A disappearing focus indicator may make it difficult for keyboard-only users to determine where the current focus is located. Users may lose track of their position while navigating through the page using the Tab key. This can affect the usability and predictability of keyboard navigation. Maintaining a visible focus indicator helps users understand which interactive element is currently selected.	
AFFECTED URL	
https://www.dosje.gov.in/about-us/ https://www.dosje.gov.in/ Throughout the website	
RECOMMENDATIONS	
The keyboard focus indicator should remain visible on the currently focused element throughout keyboard navigation. The focus should not disappear when the Tab key reaches the end of the page. The focus order and focus styling should be reviewed to ensure consistent keyboard navigation. The affected pages should be tested using keyboard-only navigation to verify that focus remains visible and predictable.	

8.25 No Mechanism to Stop or Pause Moving Content


STATUS	OPEN
REFERENCE	<u>GIGW GUIDELINES 3.0</u>
DESCRIPTION	The website contains moving content that does not provide an appropriate mechanism to stop or pause the movement. Users are unable to control the movement of the affected content through a pause or stop function. This may make it difficult for some users to read or interact with the moving information. A suitable mechanism should be provided to allow users to control moving content. The control should be easily accessible and operable.
IMPACT	The absence of a stop or pause mechanism may make it difficult for users to read or interact with moving content. Users who require additional time to process information may have difficulty accessing the content before it moves. This can affect the accessibility and usability of the website. Providing a suitable control allows users to stop or pause the movement and access the information at their own pace.
AFFECTED URL	https://www.dosje.gov.in/
RECOMMENDATIONS	A visible and accessible mechanism should be provided to allow users to pause or stop moving content. The control should be operable using both keyboard and pointer input where applicable. Moving content should remain accessible while it is paused or stopped. The affected pages should be tested to ensure that users can control the movement without loss of content or functionality.
PROOF OF CONCEPT	 The screenshot shows the homepage of the Department of Social Justice & Empowerment (DOSJNE) website. The URL in the browser is https://www.dosje.gov.in/. The page features a large video player at the top, which is currently playing a video of a group of people on a stage. The video player has a standard interface with a play button, but no visible pause or stop button is present, illustrating the issue described in the report.

8.26 Link Information Is Not Properly Conveyed by Screen Reader


STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The screen reader does not properly read the affected links on the website. The link information is not being conveyed clearly and accurately to users of assistive technologies. As a result, users may have difficulty understanding the purpose or destination of the links. The affected links should provide meaningful and accessible information to screen reader users. Link names and associated information should be properly exposed to assistive technologies.
IMPACT	Improperly announced links may make it difficult for screen reader users to understand the purpose or destination of a link. Users may have difficulty distinguishing between different links when navigating through the page. This can affect the efficiency and usability of keyboard and screen reader navigation. Providing meaningful link information helps users understand and operate links more effectively.
AFFECTED URL	https://www.dosje.gov.in/organisation/dr-ambedkar-international-centre/ https://www.dosje.gov.in/organisation/dr-ambedkar-foundation/ Throughout the website
RECOMMENDATIONS	The affected links should be implemented with clear and meaningful accessible names. Link text should accurately describe the purpose or destination of the corresponding link. Any unnecessary or ambiguous accessible names should be corrected. The links should be tested with a screen reader to verify that their purpose is clearly conveyed to users.
PROOF OF CONCEPT	 The screenshot shows a web browser displaying the 'Department of Social Justice & Empowerment' website. The address bar shows 'dosje.gov.in/organisation...'. The page content includes a sidebar with 'OTHER LINKS' (Tender, Panchteerth, Booking) and 'CONNECT & ENGAGE' (Latest Updates, Contact). The main content area is titled 'About DAIC' and describes the Dr. B.R. Ambedkar International Centre. A 'Know More' button is highlighted with a red box. The page also features a 'VISION' and 'MISSION' section at the bottom.



8.27 Labels Missing for Input Fields

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	Labels are missing for the affected input fields on the website. The input fields do not provide clear and properly associated labels to identify their purpose. This may make it difficult for users to understand what information is expected in each field. The labels should be programmatically associated with their corresponding input controls. Appropriate and descriptive labels should be provided for all applicable form fields.
IMPACT	Missing labels may make it difficult for users to identify the purpose of input fields, particularly when using assistive technologies. Screen reader users may not receive sufficient information about what data should be entered into a field. This can affect the understanding and usability of forms on the website. Providing clear and associated labels helps users complete forms accurately and efficiently.
AFFECTED URL	https://www.dosje.gov.in/ https://www.dosje.gov.in/schemes-services/?org=mosje Throughout the website
RECOMMENDATIONS	Descriptive labels should be provided for all applicable input fields. Each label should be programmatically associated with its corresponding form control. The labels should clearly indicate the expected information or purpose of the field. The affected forms should be tested using a screen reader and keyboard navigation to verify that labels are correctly conveyed.
PROOF OF CONCEPT	

8.28 Status Messages Are Not Properly Conveyed by Screen Reader

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	The screen reader does not properly read the status messages displayed on the website. The status information is not being programmatically conveyed to users of assistive technologies. As a result, users may not be informed when a relevant status or update occurs on the page. The affected status messages should be properly exposed to assistive technologies. Appropriate programmatic mechanisms should be used to ensure that status information is conveyed without requiring focus changes.
IMPACT	Failure to convey status messages may prevent screen reader users from receiving important updates or feedback generated by the website. Users may not be aware when an action has been completed or when the status of a process has changed. This can affect the usability and accessibility of interactive functionality. Properly announced status messages help users understand changes occurring within the interface.
AFFECTED URL	https://www.dosje.gov.in/?s=ACSS&e_search_props=370146a-260
RECOMMENDATIONS	Status messages should be implemented so that they are programmatically exposed to assistive technologies. Appropriate ARIA live regions or other suitable accessibility mechanisms should be used where applicable. The messages should be announced without unnecessarily moving keyboard focus. The affected functionality should be tested with a screen reader to verify that status updates are clearly conveyed to users.
PROOF OF CONCEPT	 The screenshot shows the Government of India Department of Social Justice & Empowerment website. The search bar at the top is highlighted with a red box. Below the search bar, the search results for 'ACSS' are displayed, showing 'No results found.' with a magnifying glass icon. The URL in the browser's address bar is also highlighted with a red box.

8.29 Some Content Is Not Properly Conveyed by Screen Reader

STATUS	OPEN
REFERENCE	GIGW GUIDELINES 3.0
DESCRIPTION	
The screen reader does not properly read or convey some content available on the website. Certain elements are not being presented clearly to users of assistive technologies. This may make it difficult for users to understand or interact with the affected content. The affected elements should provide appropriate semantic information to assistive technologies. The website should ensure that all relevant content is properly accessible through screen readers.	
IMPACT	
Improperly conveyed content may make it difficult for screen reader users to understand the information presented on the website. Users may not receive the complete or correct information from affected elements. This can affect navigation, interaction, and overall accessibility of the website. Properly exposing content and its associated semantics helps users access the information effectively.	
AFFECTED URL	
https://www.dosje.gov.in/ Throughout the website	
RECOMMENDATIONS	
The affected content and interface elements should be reviewed to ensure that their names, roles, states, and relevant information are properly exposed to assistive technologies. Appropriate semantic HTML and accessibility attributes should be used where required. The implementation should be tested with a screen reader to identify and correct incorrectly announced or unannounced content. All relevant elements should provide clear and meaningful information to assistive technology users.	

8.30 Error Identified in HTML and CSS Validation

STATUS	OPEN																																												
REFERENCE	GIGW GUIDELINES 3.0																																												
DESCRIPTION	The website contains errors identified during HTML and CSS validation. These errors indicate that the website code does not fully conform to the applicable markup and stylesheet validation requirements. Such errors may affect the consistency and proper rendering of web pages across different browsers and environments. The identified HTML and CSS validation errors should be reviewed and corrected to ensure that the website is implemented using valid and properly structured code.																																												
IMPACT	HTML and CSS validation errors may affect the consistency, maintainability, and rendering of website content. In some cases, invalid markup or stylesheet code may cause differences in how content or interface elements are displayed across browsers. These issues may also affect the proper interpretation of page structure by certain technologies. Correct and valid code helps maintain consistent presentation and improves the overall reliability of the website.																																												
AFFECTED URL	https://www.dosje.gov.in/																																												
RECOMMENDATIONS	Review the website using appropriate HTML and CSS validation tools and identify all reported errors. Correct invalid or improperly structured HTML elements, attributes, and CSS declarations in accordance with applicable standards. After remediation, revalidate the affected pages to confirm that the identified errors have been resolved and that the website maintains consistent rendering across supported browsers.																																												
PROOF OF CONCEPT	HTML errors — 51 total (W3C Nu Html Checker) Grouped by issue type; every affected line number is listed. <table><tr><th>#</th><th>Error</th><th>Severity</th><th>Line numbers (in served HTML)</th></tr><tr><td>1</td><td>Duplicate ID "dip0_3842_4326" (repeated inline SVG with hard-coded ID)</td><td>High</td><td>2548, 2591, 2634, 2686, 2738, 2779, 2831, 3761, 3793, 3825, 3857</td></tr><tr><td>2</td><td>"aria-labelledby" / "aria-label" on a <div> that has no appropriate role</td><td>Medium</td><td>988, 1010, 1054, 1216, 1266, 1376, 1426, 1698, 3220, 3365, 3716, 5011</td></tr><tr><td>3</td><td>Bad value "combobox" for attribute "role" on <input> (search widget)</td><td>Medium</td><td>929, 966, 5266</td></tr><tr><td>4</td><td>Attribute "aria-expanded" not allowed on <input> at this point</td><td>Medium</td><td>929, 966, 5266</td></tr><tr><td>5</td><td>Element <div> not allowed as child of <output></td><td>Medium</td><td>931, 968, 5288</td></tr><tr><td>6</td><td>Duplicate attribute "loading" on </td><td>Low</td><td>1825, 1890, 1954, 2020, 2085, 2149, 2213, 2251, 2302, 2340, 2404</td></tr><tr><td>7</td><td>Heading level skipped — <h4> follows <h2> (skips 1 level)</td><td>Medium</td><td>1600, 3355, 3547, 3751</td></tr><tr><td>8</td><td>Heading level skipped — <h6> follows <h3> (skips 2 levels)</td><td>Medium</td><td>2476, 4733</td></tr><tr><td>9</td><td>CSS: "box-shadow: 0" is not a valid box-shadow value</td><td>Low</td><td>507</td></tr><tr><td>10</td><td>A <style> element in <body> must be the first child of its parent</td><td>Low</td><td>1500</td></tr></table>	#	Error	Severity	Line numbers (in served HTML)	1	Duplicate ID "dip0_3842_4326" (repeated inline SVG with hard-coded ID)	High	2548, 2591, 2634, 2686, 2738, 2779, 2831, 3761, 3793, 3825, 3857	2	"aria-labelledby" / "aria-label" on a <div> that has no appropriate role	Medium	988, 1010, 1054, 1216, 1266, 1376, 1426, 1698, 3220, 3365, 3716, 5011	3	Bad value "combobox" for attribute "role" on <input> (search widget)	Medium	929, 966, 5266	4	Attribute "aria-expanded" not allowed on <input> at this point	Medium	929, 966, 5266	5	Element <div> not allowed as child of <output>	Medium	931, 968, 5288	6	Duplicate attribute "loading" on 	Low	1825, 1890, 1954, 2020, 2085, 2149, 2213, 2251, 2302, 2340, 2404	7	Heading level skipped — <h4> follows <h2> (skips 1 level)	Medium	1600, 3355, 3547, 3751	8	Heading level skipped — <h6> follows <h3> (skips 2 levels)	Medium	2476, 4733	9	CSS: "box-shadow: 0" is not a valid box-shadow value	Low	507	10	A <style> element in <body> must be the first child of its parent	Low	1500
#	Error	Severity	Line numbers (in served HTML)																																										
1	Duplicate ID "dip0_3842_4326" (repeated inline SVG with hard-coded ID)	High	2548, 2591, 2634, 2686, 2738, 2779, 2831, 3761, 3793, 3825, 3857																																										
2	"aria-labelledby" / "aria-label" on a <div> that has no appropriate role	Medium	988, 1010, 1054, 1216, 1266, 1376, 1426, 1698, 3220, 3365, 3716, 5011																																										
3	Bad value "combobox" for attribute "role" on <input> (search widget)	Medium	929, 966, 5266																																										
4	Attribute "aria-expanded" not allowed on <input> at this point	Medium	929, 966, 5266																																										
5	Element <div> not allowed as child of <output>	Medium	931, 968, 5288																																										
6	Duplicate attribute "loading" on 	Low	1825, 1890, 1954, 2020, 2085, 2149, 2213, 2251, 2302, 2340, 2404																																										
7	Heading level skipped — <h4> follows <h2> (skips 1 level)	Medium	1600, 3355, 3547, 3751																																										
8	Heading level skipped — <h6> follows <h3> (skips 2 levels)	Medium	2476, 4733																																										
9	CSS: "box-shadow: 0" is not a valid box-shadow value	Low	507																																										
10	A <style> element in <body> must be the first child of its parent	Low	1500																																										

CSS errors — 7 total (W3C Jigsaw, inline styles only)

Only row 1 is a genuine defect. Rows 2–7 are flagged because the validator's CSS3 profile does not include the SVG property "fill" or the standard property "pointer-events"; both work correctly in browsers.

#	Line	Selector / context	Validator message	Assessment
1	413	<u>.home-org-items-sec</u> <u>portals-links-sec</u> <u>.elementor-icon-list-item</u> > a: hover	"0" is not a "box-shadow" value	Real defect — fix to "none" or "0 0 0 0"
2	257	<u>.organization-icon</u> <u>svg</u> , <u>.organization-icon</u> path	Property "fill" doesn't exist	Validator limit — "fill" is valid SVG-in-CSS
3	465	<u>.white-primary-btn</u> path	Property "fill" doesn't exist	Validator limit — valid in practice
4	597	<u>.btn-elementor-primary-outline</u> <u>.elementor-button</u> <u>svg</u> path	Property "fill" doesn't exist	Validator limit — valid in practice
5	479	<u>.white-primary-btn</u> <u>elementor-button:disabled</u>	Property "pointer-events" doesn't exist	Validator limit — standard property
6	483	<u>.white-primary-btn</u> <u>elementor-button:disabled</u>	Property "pointer-events" doesn't exist	Validator limit — standard property
7	838	<u>.ccps-banner-slider</u> <u>ccps-nav-btn</u> <u>swiper-button-disabled</u>	Property "pointer-events" doesn't exist	Validator limit — standard property

CONFIDENTIAL

9. General References

[1] <https://guidelines.india.gov.in/introduction/>

[2] <https://www.w3.org/TR/WCAG21/>

THE END
OF
DOCUMENT