



π0.5 Action Expert — roofline by operator



Each point pools repeated calls of one operator. Unplotted IDs (no valid FLOP/byte point): 13, 14, 15, 16.

Historical Omni 1826509 | 10 denoising steps | image masks false, prefix=150 | NOT the new 3-camera workload

0913/30 | plotted 2026-09-13T20:22:40+08:00